# Douglas County Surveyor's Record of Government Corners Renewed

T 25 T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

116

Section corner for Secs. 13 and 24 only, T.25-3
Found - 1943 GLO brass cap, properly mkd., firmly set.
Orig. 24" now 38" Fir alive with large pitched over scar, bears S.55°E., 17.8 ft.
Orig. 30" now 47" Fir stump (7 ft. high) with well healed scar, bears S.21°W., 17.2 ft. (rec. 15.8 ft. Ties to face fairly good)
Orig. 18" now 16" rotted fir snag (10 ft. tall) bears N.38°W., 84.6 ft. (Rec. 85.1 ft.) scribed "T25S R3W S13 BT" visible on east side of tree.
9" now 12" hemlock per 1943 resurvey, down with well healed scar bears N.38 1/2°W., 12.5 ft. to root hole.
New BT's - 13" Hemlock bears S.1°E., 36.8 ft. scribed "T25S R3W S13 CS BT" in double blaze.
10" Hemlock bears N.87°W., 18.0 ft. scribed "T25S R3W S13 CS BT" in double blaze.
9" Hemlock bears N.45°W., 62.0 ft. scribed "T25S R3W S13 CS BT" in double blaze.
Note - Corner lies in cut lines west of rock Rd. approx. 50 ft.

RE-ESTABLISHED, SEE CORNER NO. # 129

Gregory Quibell
Deputy, Douglas County Surveyors Office
Witnesses: Terrie Plouff/ Teresa Buley
Oct. 13, 1981
C.S. 61/29

10/13/81

117

FD OK S. NESS 10/95 4123-3 A B

1/4 Corner common to Secs. 12 & 13.
Found - 1962 Cadastral B.C. under 10-inches of dirt and rock with steel fence post alongside.
BTs. - 39" fir stump bears S.54°W.,12.5-ft.
16" hemlock bears South,28.4-ft. (broken off at stump).
New BTs.- 5" D. Fir bears N.89°W.,24.6-ft. (scribed)
5" D. Fir bears S.20°E.,39.0-ft. (scribed).
*Note: brass disc on each face with "RLS 498"
Note - Corner sets alongside a small dry stream bed - entire area is covered with 1 - 4 feet of dirt & rock that has washed in from up above.

REN. # 78

Howard Johnstone
February 5, 1982
C.S. 58/188

2/5/82

118

Southwest corner of Section 31 only of T.24-1
Found - 27" fir, N.64 1/4°E., 44.2 ft. OBT.
17" fir, N.18 1/4°E., 27.1 ft. (1951 Cadastral resurvey)
8" chinquapin, S.13 1/4°E., 13.2 ft. OBT
Landing construction eliminated these BTs after the corner was referenced out. Monument and BTs were in the middle of a proposed landing to be constructed in a logging clear cut unit. I referenced out the B.C. and after the landing was built and the unit logged:
I Re-set- the brass cap from my references and scribed 2 BTs to the west which is the only area with remaining timber. Brass cap mkd: "U.S. General Land Office Survey"
(Cap was reset in large mound of rocks.)

T24S
R1W
S 31
T 25 S R 2 W
S 1
1951 191

New BTs - 9" D. fir, S.45°W., 102.3 ft. scribed S1 L 28 T25S R2W BT.
26" S. Pine, S.80°W., 105.9 ft. scribed S1 L 28 T25S R2W BT.
Note: Corner sets on a step landing at end of spur road and at base of cut slope for landing. Bts are at toe of road fill slope.

Howard Johnstone
For: Roseburg Lbr.
Sept. 24, 1985
C.S. 63/26

9/24/85

119

1/4 Corner for Sections 20 and 29
Found - A 1962 BLM 3¼" Brass cap on a 2½" I.P. firmly set, protruding 6" above ground.
Top of apparent orig. basalt corner stone protrudes 2" above ground lies along NW edge of I.P. stone, is firmly set. Did not disturb to look for marks.
Orig. BT, a 14" now 19" dia. 4 ft. high shattered rotted D. fir stump with fragmentary scribing "20" bears N.25°E., 45.0 ft. (Agrees well with orig. brg, dist. 44.2 ft. is a face measurement)
Orig. BT, a 6" now 19" dia. dead 50 ft. high D. fir snag with a fully healed single blaze bears S.51½°E., 35.6 ft. (Rec. S.48°E orig. and S.50°E., per 1962 resurvey, dist. agrees well with rec.)
1962 BT, a 5" now 9" dia. dead D. fir with a fully healed single blaze bears N.49½°W., 13.2 ft. (agrees with record)

Douglas County Surveyors Office
Randall Smith
Stephen Flause
Feb. 25, 1986
C.S. 62/31

CONT NEXT PAGE