Douglas County Surveyor's Record of Government Corners Renewed

T. 25 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Cont'd.

Douglas County
Surveyors Office
Randall Smith, Deputy
Stephen Flause
Mar. 30, 1995
C.S. file 64/58-8

129

New Accessories - 5" dia. Hemlock, double blazed and scribed "X BT", bears S.0½°W., 66.7'.
4" dia. D.Fir, double blazed and scribed "X BT", bears N.36½°W., 24.5'.
3" dia. D.Fir, double blazed and scribed "X BT", bears S.68°W., 22.1'.

130

see ren. # 93

¼ cor. of S. 16 & S. 15
Mon. Fd. - 2½" dia. DCSO brass cap on a 1½" o.d. iron pipe is found 12" below ground. Orig. cor. stone not fd.
Accessories FD. -
Both orig. BT's are gone
10" now 14" dia maple with a partially healed rotted double blaze, no scribing visible bears N.49°E., 45.4'. (rec. N49°E, 44.5')
14" now 24" dia maple, with a fully healed double blaze, bears S.88¼°W., 52' (rec. West 52.8')
18" now 31" dia cedar, with a fully healed single blaze, bears S.32°W., 109.1' (agrees with rec.).
16" now 24" dia maple, with a fully healed singe blaze, bears N.31°E., 32' (rec. N.29°E., 32').
New Accessories -
Set a 5/8" by 60" long IR along north edge of BC/IP protrudes 3' above ground. set to help in location of BC/IP.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Mar. 29, 1995
C.S. File 64/58-9

131

see ren. #24

Sec. cor of 13,14,23 & 24
Mon. FD. -3½" dia BLM brass cap on a 2½" O.D. Iron pipe protrudes 5" above ground (1962 BlM).
1 3/4" I.D. iron pipe protruding 14" above ground. is found along east edge of BLM BC/IP.
Accessories FD. -
6" now 20" dia 5' high D.Fir stump with a fully healed blaze, bears N.12°W., 13.9' (agrees with rec) OBT
12" now 14" dia 3' high D.Fir stump with a fully healed single blaze, bears N.31°E., 25.4' (agrees with rec.).
14" now 20" dia 3½' high D.Fir stump with a fully healed single blaze, bears S.9½°E., 15.5' (rec. S.9½°E., 14.2')
9" now 9" dia, 20' high D.Fir snag with a fully healed double blaze, bears S.52°W., 17.8' (rec. S.52°W., 18.5' dist. measured to trunk)
14" now 14" dia. 3' high D.Fir stump, scribing found "T25S" lower blaze is healed, bears N.57°E., 52.1' (agrees with rec.)
New Accessories -
7" dia. Hemlock, double blazed and scribed "T25S R2W S13 CS BT", bears N.59°E., 30.1'.
7" dia. D.Fir, double blazed and scribed "T25S R2W S24 CS BT", bears S.65½°E, 21.2'
22" dia. D.Fir, double blazed and scribed "T25S R2W S23 CS BT", bears S.9°W., 27.7', (old line blazes on north and south trunk)
4" dia. D.Fir, double blazed and scribed "X BT" bears, N.71°W., 25.7'.

132

Closing cor. of sec. 18 & 19
Mon. Fd. -2½" dia GLO brass cap on a 2" O.D. iron pipe protruding 12" above ground. (1943 GLO)
Accessories Fd. -
5" now 12" dia., 25' high cedar snag with a partially healed rotted single blaze, scribing visible "T25S R2W S18" and a fully healed double blaze on south trunk, bears N.66½°E., 18.4' (agrees with 1943 rec,.)
60" now 64" dia. 2' high rotted D.Fir stump with evidence of a lower blaze, no scribing found, bears S.70°E., 35.6' (agrees wiht rec.)

(Cont. Next Page)