Douglas County Surveyor's Record of Government Corners Renewed

T. 25 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued) (#60)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 — T 25 S R 8 W; ¼ S 29 / S 32

New BT's: 13" Hemlock N. 39* E. 12.7 ft. mkd: ¼ S29 CS BT.
9" D. Fir S. 13* E. 9.2 ft. mkd: ¼ S32 CS BT.
Ridge call to west fit very well with orig. call distances. This corner lies on very steep easterly slope about 200' E. of ridge, course NW & SE.

10/2/68

\- - - - - - -

61

¼ Corner to Sections 7 and 18.
Found - Orig. 18" Fir, now dead & badly decayed, S.23*E. 7.9 ft.(Rec.S37E) scribe visible on unhealed blaze.
Orig. 24",now 38" Hemlock, alive, N. 11* W. 30.4 ft., shows fair scar. Rescribed "¼ S7 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 — T 25 S R 8 W; ¼ S 7 / S 18

New BT: 18" Hemlock S. 4* W. 34.2 ft. mkd: ¼ S18 CS BT.
This corner lies on steep east slope of main divide btwn. bottom creek and Lake Creek about 66 ft. east of ridge top.

10/3/68

\- - - - - - -

62

Closing Corner to Sections 7 and 18, T25-8W.
Found - Orig. 10",now 20" Hemlock, alive, N.43½*E. 34.3 ft., shows good scar. Rescribed: "T25S R8W S7 CC CS BT".
Orig. 8",now 9" Hemlock, alive, S.22½*E. 14.5 ft., scribe marks visible on unhealed blaze. We notch blaze overgrowth and count 50+ rings.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 — R 9 W; T 25 S: S 7 / S 18; R 8 W

New BT: 11" Hemlock S.43½*E. 28.9 ft. mkd: T25S R8W S18 CC CS BT.
This corner lies on steep N.E. slope 50 ft. N. of small spur, ridge sloping N.W.

\- - - - - - -

63

Section Corner to Sections 33 and 34, T25-8W. and Section 4 and 3, T26-8W.
Found - Orig. 15",now 30" Cedar, alive but leaning badly, S.85*E. 2.6 ft., faint scar.
Orig. 20",now 36" Cedar, 8' high snag, S.40*W.(Rec.S40E) 3.3 ft., open & find reverse scribe.
Orig. 12",now 22" Cedar, alive, N.88*W. 5.3 ft., shows faint scar. Rescribe: "T25S R8W S33 CS BT."
No trace N. E. Maple Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 — T25S / T26S R8W; S 33 / S 4 | S 34 / S 3

New BT's: 60" D.Fir S.25*E. 30.8 ft. mkd: T26S R8W S3 CS BT.
26" Hemlock S. 16* W. 32.2 ft. mkd: T26S R8W S4 CS BT.
8" Hemlock N. 41* E. 21.2 ft. mkd: T25S R8W S34 CS BT.
This corner lies on very steep west slope about 150 ft. E. of bench.

\- - - - - -

64

¼ Corner to Section 36, T25-8W. and Sec. 1, T26-8W.
Found - Orig. 30" Fir, now 48" Stump, S.35*E. 26.4 ft., only small trace of bark scrbe remains. Cruiser's marks & yellow tag on S.E. BT., recorded in Forest appraisal survey, dated Nov., 1951 by Lecklider & Givens.
No trace of old N.E. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 — T25S / T26S R8W; ¼ S 36 / S 1

New BT's: 14" Hemlock S.68*W. 50.4 ft. mkd: ¼ S1 CS BT.
10" Cedar N. 87*E. 28.4 ft. mkd: ¼ S36 CS BT.
Note - this corner lies on very steep N. slope about 100' S. of creek, course E. We put yellow line tag at creek about 100' N. of corner.

9/26/68

\- - - - - - -

Vernon "Ray" Tracy
Jack Heritage & V. Perron
September & October, 1968
C. S. File No. 54/72