Douglas County Surveyor's Record of Government Corners Renewed

T. 25 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Weyerhaeuser Co.
By Donald L. Peel
April, 1967
C. S. File No. 55/30

Closing Corner common to Sections 6 & 7, T25-8W. 1
Found - GLO Survey Record - Post -- Gone.
30" hemlock N. 20 3/4° E. 67 lks., now 36" hemlock, scribe visible.
20" cedar S.83°E. 55 lks., now 24" Cedar, face not quite closed, scribe visible.
Set - 4' x 3/4" Pine, 3' in ground & square post.
Both BT's. in good shape, so put Weyerhaeuser Co. plates with call distances & bearings on the orig. BT's.

\- - - -

East ¼ Corner common to Section 1, T25-9W. 2
Found - GLO Survey Record, Sandstone -- Gone.
48" fir N.87½°E. 32 lks., now fir windfall, chopped open. Scribe visible, supposedly markings destroyed in 1911 retracement, but not so.
50" fir S. 85°W. 29 lks., now 50" fir, closed face.
Set - 4' x 3/4" Pipe, 2½' in ground and square post.
Re-referenced with "W" nails & plates only: 50" fir S.84°W. 17.0 ft.
60" fir N.47°W. 5.3 ft.

\- -

Hiatus Corner common to Secs. 1 and 6, T25-8 & 9W. 3
Found - GLO Survey Record, Post -- Gone.
36" fir S.30°E. 93 lks., now 37" fir, closed face, not S30E but S61E.
40" fir S61W 20 lks., now 42" fir, closed face, not S61W, but S30W.
Note - From the call distances & the direction of the faces on the BT's, I would say the bearings in the orig. field notes were reversed.
Set - 4'x 3/4" pipe, 2½! in the ground & square post.
Re-referenced with "W" nails & plates only: 42"Fir S.35°W. 11.7 ft.
18" cedar N.47°W. 12.5 ft.

Closing corner common to Secs. 1 and 6, T25S, R8 & 9W. 4
Found - GLO Survey Record, Post -- Gone.
60" cedar S.86°W. 11 lks., now cedar snag, scribe visible.
12" cedar S.60°E. 78 lks., now 16" cedar already chopped open, scribe visible.
Set -4' x 3/4" pipe, 3½! in ground & square post.
Re-referenced with "W" nails & plates only": 30" hemlock S.49°E. 65.6 ft.
50" fir S.28°W. 44.9 ft.

\- - - - - - - - - - - -

Sept '68 MICROFILM TO HERE 10/67

V. R. Tracy
& Crew
10/3/68
C. S. File
No. 54/72

Closing Corner to Sections 7 and 18 only, T25-8W. 5
Found - Orig. 10", now 20" Hemlock, alive, N.43½*E. 34.3 ft., shows good scar. Rescribed: "T25S R8W S7 CC CS BT".
Orig. 8", now 9" Hemlock, alive, S.22½*E. 14.5 ft., scribe marks visible on unhealed blaze. Notch blaze overgrowth & count 50+ rings
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 — R 9 W | T 25 S, S 7 / S 18 | R 8
New BT: 11" Hemlock S.43½*E. 28.9 ft. mkd: T25S R8W S18 CC CS BT.
This corner lies on steep N.E. slope 50' N. of small spur, ridge sloping N.W.
10/3/68

\- - - - - - - -

East ¼ Corner to Section 12, T25-9W. 6
Found - Orig.48" Fir, now 51" sawed stump, S.45*W. 6.6 ft., we chop open & find "¼" scribe.
No trace of corner stone or other Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 — R 9 W | ¼ | T 25 S, S 12 | R 8 W
(½" Steel Pipe bears S.47*E. 2.8 ft.)
New BT's: 51" Fir Stump S.45*W. 6.6 ft., mkd: "¼ S12 CS BT".
42" Fir Stump N.57*W. 55.6 ft. mkd: "¼ S12 CS BT.
Corner lies on steep southerly slope in large clear cut area and 75 ft. south of Weyerhaeuser Road #2000.

\- - - - - -

Section Corner to Sections 12 and 13 only, T25-9W. 7
Found - Sandstone called for with 4 notches on S. & 2 notches on N.
Orig. 60", now 68" Fir, alive, N.70*E. 7.9 ft., shows good scar.
Orig. 64", now 70" Fir, alive, S.36¼*E. 21.1 ft., shows good scar.
Note - The BT's. above were marked before the C.C. of Secs. 7 and 18.

(continued over)

Jan 78