Douglas County Surveyor's Record of Government Corners Renewed

26 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

21

N.E. CORNER D.L.C. #42
Donation of F.R. Hill. - MAR. 1964 - NO TRACE EITHER ORIG. B.T. - STONES SCATTERED DID NOT RENEW - SEE C.S. 49/125 LL

Set a stone and mound of stone, from which a bl. oak 16" diam. bears n 59¼° W 2.21 chains,

Nov. 1899. In presence of W.B. Lamb, Lamb jr. W. Grange jr. Doc. Hill.

original B.T. had fell down, but we found the B.T. on it, also verified by measure South 17.36 chains to interrior corner.

All the original B.T. have been cut down, marks were found on three of the remaining stumps, all agreeing in direction and distance with the field notes. Present. Lee Barker and John Fegles Mar. 20, 1900.

Vol. 2 Pg. 85 C.S. Vol. 2 Page 87

22

¼ Sec. Cor. Between 36 - 1 (corrected 60.14) THIS COR. NOT FD. 1964 NEG T26 & 27S R5W

Set post and raised mound of stone from which
A B. Oak 8" Diam., bears S 42¾° E 29 lks. dist.
A B. Oak 18" daim., bears N 1° E 62 lks. dist.
May 14, 1909, The original B. T. in the SE is standing but dead, the NW B. T. is fallen down.

Vol. 1 Pg. 67

23

SW Cor. C 1 (corrected #17) set post and Brick by stump of B. T.
Set by Wm. Theil Ict. 31, 1885
New B. T's.
W. Oak 30" Diam., bears N 86½° W 3.18 chs.
B. Oak 30" diam., bears S 43½° W 2.71 chs.

WOODFORD F.B. W28, Pg. 5

23A

~~S/W/Cor./DLC#/43/~~
~~Vol./1/Page/67/////6x6x16/Basalt/Stone~~
Cor. Sec. 22, 23, 26 & 27 Set ¾" iron pipe E. S. Woodford
BT's: 10" W. OAK S.67½°W 145.6 ft. April 1953
10" MADRONE S.36½°E. 139.2 ft.

J. W. Byron, Dep. Co. Surveyor
R. Irving May 24, 1954
John Fee Work done for Darley Ware.
Filed in 46/6.

24

¼ sec. corner to sec. 30, T26S, R5W., and sec. 25, T26S, R6W. 150
Found: - REN. No. 18
4 inch by 4 inch by 5 foot Cedar post. Also a 6 inch by 6 inch square sandstone rock, 6 inches under surface mkd ¼ S. Also found 5/8 inch rod.
Blazed and scribed:
10 inch W. O., S.66½°E., 483.5 feet dist., mkd. ¼S 30 CS BT.
RE-RENEWED, SEE CORNER NO.
RE-NOT RENEWED - 2/4/78 - L. MONSEN - COUNTY - C.S. 60/11

25

¼ sec. corner to sec. 18, T26S, R5W., and sec. 13, T26S, R6W. #162
Set 1½ inch iron pipe with brass cap mkd County Surveyor's Office ¼S 13/18 T26S R6W R5W 1954. Set at wire fence corner.
NW corner of Farmers livestock concrete block building bears S.56°E. 281.8 feet dist.
Wilbur beacon bears N.37°23'E.
RE-RENEWED, SEE CORNER NO.
CORNER DESTROYED BY CONSTRUCTION SEE M 106-18 G. BAUGHMAN 5/88

Edwin S. Woodford
Wit: M. E. Godfrey
August, 1953.
C. S. File No. 42/109.

26

Witness corner to Meander corner on left bank of N. Umpqua River between Secs. 21 and 22.
No trace of old meander corner found. Distance from witness corner to ¼ sec. corner to secs. 21 and 22 would put this corner in the river as it exists now.
Line between secs. 21 and 22 was projected through corner of secs. 21, 22, 27 and 28 and Witness corner to ¼ corner to secs. 21 and 22.
Set a ½ inch x 24 inch iron pipe 130 feet from present edge of water for witness corner to meander corner.
Mark 2 B. T.s:
18 inch Maple, N.50°45'E., 59.9 feet, scribe W. C. M. C. 622 B. T.
20 inch Maple, S.87°45'W., 14.9 feet, scribe W. C. M. C. 622 B. T.

Edwin S. Woodford
Wit: M. E. Godfrey
August, 1952.
C. S. File No. 42/114.

27

Witness corner to ¼ sec. corner to secs. 21 and 22.
Found both old B. T.s:
8 inch Y. Oak, S.25°E., 113 lks. (Now 24 inches).
6 inch Y. Oak, S.18½°W., 201 lks. (Now 20 inches).
Chopped out Southeast tree and found scribe marks in good condition - wood still alive and sound.
Set iron stake for corner.
SEE REN. #132A
Marked 2 new trees for corner:
18 inch Douglas Fir, S.34°30'E., 53.1 feet, scribe ¼ S W C 622 B. T.
8 inch B. Oak, S.45°W., 59.9 feet, scribe ¼ S W. C. 622 B. T.
FOUND O.K. SEPT. 1966 BY WM. EMSTAD SEE M 32-30