Douglas County Surveyor's Record of Government Corners Renewed

T 27 T. S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

155

C O N T.--------

Karen Reed
P. Earle - F. Silagy
Doug. Co. Surveyors
Office C.S. 60/17

No new monument set.
BT's- A 7" White Oak bears N.27°E., 365.2 ft. with double blaze marked "T27S R6W S24 CS BT".
A 19" Ash bears N.58°W., 230.0 ft. with double blaze marked "T27S R6W S23 CS BT"

1-79 12/13/78

156

Northwest corner DLC #64
Found - 5/8" I.R. lying loose on surface of ground and a scattered mound of stone from Ren. #34. A brass cap from Ren. #150 is missing.
An orig. 15" B. Oak now a 26" stump bears N.48°W., 15.8 ft. some evidence of a blaze but center is rotted and burned, no scribing evident.
An orig. 20" B. Oak now 42" stump bears N.55°E., 36.3 ft. some evidence of possible healed blaze. center of stump is rotted and burned, no scribing evident. Above distances were measured from orig. face diameters of stumps to center of remaining evidence of mound of stone (see renewal procedure)

Steve Flause
Douglas County
Surveyors Office
Shawn Means - Witness
March 25, 1980
C.S. 61/6

A 14" now a 15" B. Oak bears S.5°E., 87.0 ft. (Rec. S.4°E., 87.0) with a double blaze scribed "DLC 64 T27S R6W CS BT" and partially healed. Ren. #150
A 15" now 16" Madrone bears N.42°E., 64.5 ft. (as per record) with a double blaze scribed "S6 T27S R6W CS BT" and partially healed.
Note: After checking record distances from cente- of root crowns of orig. BT stumps and finding bearings to be off it is assumed orig. distances were made as face measurements; checking this assumptio by measuring and intersecting orig. record distances from orig. 10" and 20" BT diameters it is found that bearings to BTs are of record and corner location falls near center of remains of mound of stone from Ren. #34; this location is accepted as the corner position.
Set - A Doug. Co. Surveyors Office bronze drill cap in sandstone bed-rock over which we place the 5/8" x 30" I.R. (Rec. #34) in amound of stone measuring approx. 2.5 ft. tall. Cap is marked T27S NW DLC 64 R6W 1980.
New BT tags are placed on OBT stumps. Corner is on north bank of Melrose Rd. #13 at route #955.

3/25/80

157

Southeast corner DLC #57
Found - A 1977 Doug. Co. Surveyors brass cap properly marked, on a Ren.151 1" x 30" iron pipe firmly set and protruding 3" from ground.
A 5/8" x 36" iron rod is set at the north east edge of the cap. Top of iron rod is 1/2" higher than top of brass cap. Ren. #36
Cap is 0.3 ft. east of corner of new fences running north and west
Cap is 10.6 ft. south of older fences running south and east.

Stephen Flause
Deputy - Doug.
Co. Surveyors
Office.
Witness: Shawn
Means
June 19, 1980
C.S. 61/6

BT's - Search for orig. BTs made, none found.
Tree from renewal #36 not found.
From Ren. #60, found a 16" now 20" W. Oak bears N.84°W., 13.2 ft. (Rec. West, 13.2 ft.) Has well healed double blaze, no scribing visible.
A 12" now a 14" Myrtle bears N.55 1/2°W., 27.3 ft. (Rec. N.46"W., possibly mag. attraction from fence was not adjusted for, 27.3 ft.) Has partially healed double blaze with scribing "DLC 5" visible.
Set - Existing monument at position determined by Lecklider (Ren. #60) is perpetuated with a new accessory as follows:
An 8" Ash tree bears N.70°E., 25.6 ft. and is scribed "SE DLC 57 CS BT" on a double blaze.
All trees are retagged with DCSO BT tags marked with bearings and distances as determined in this renewal.

6/19/80

O V E R