Douglas County Surveyor's Record of Government Corners Renewed

T 29 T.S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21091

103

1/4 Corner for Sec. 34 only, (South) of T28-2.

Found - Orig. corner stone 12"x12"x18" marked "1/4". Stone is loose & lying at top of road cut, directly up-slope from where I have determined the true corner point to be.
A 30" Fir stump bears N.36°30'W., 53.46 ft. (Rec. N.81°30'W., 53.46 ft.) scribing visible on partly healed blaze which does face corner, "1/4 S34 BT".
Stump hole bears N.35°E., 21.12 ft. (Rec. N.36°E., 21.12 ft.)
Corner for Secs. 3 and 2 only, T29-2, bears East 258.01 ft. (Rec. S.89°58'E., 253.44 ft.).

Set - Corner falls in ditch line of road, so I SET a 5/8" x 24" iron rod at corner point. (F.S. Road #274).

New Accessories:
A 11" D. Fir bears N.45°30'E., 14.0 ft. scribed "1/4 S34 CS BT" on a double blaze.
A 12" D. Fir bears N.9°W., 12.5 ft. scribed "1/4 S34 CS BT" on a double blaze.
I bury the original corner stone between the new BT's. 4" of the stone is above ground & the "1/4" is facing North. The stone bears N.19"E., 12.1 ft.
A 2 1/2" brass cap on a 1" I.P. bears East 70.0 ft. from corner point, stamped: County Surveyor's Office T28S R2W
1978 1/4 S 34
W.C.
West
70.0'

Dennis Gaylord, U.S.F.S.
Deputy, Doug. Co. Surveyors Office
Witness: Randal Lopez
April, 1978
C.S. 59/46

4/6/78

104

Section Corner for Secs. 34 and 35 only, T28-2.

Found - Orig. corner stone, 16"x14"x5", set firmly in the ground. Stone is marked with 2 grooves on the East edge and 4 grooves on the West edge.
A 32" D. Fir bears N.75°E., 23.76 ft. (Rec. N.73°45'E.) has a healed scar.
A 6" Chinquapin is down. Stump bears N.50°W., 21.4 ft. (Rec. N.49°30'W., 21.78 ft.) Scribing visible on Chinquapin log, "T28S R2W S34 BT".
Placed BT signs on both trees.

Set - Moving the corner stone aside, I SET in its place a 2 1/2" Brass cap on a 1" I.P. stamped County Surveyor's Office 1978
T 28 S R 2 W
S 34 S 35
I bury corner stone alongside iron pipe.

New BT - A 17" D. Fir bears N.5°W., 44.4 ft. scribed "T28S R2W S34 CS BT" on a double blaze. Placed a county BT sign on Fir.

4/13/78

105

1/4 Corner for Sec. 2 only. (North)

Found - 2 1/2" Brass cap stamped U.S. General Land Office Survey 1/4 S2 1917, on a 1" I.P. set solidly 12" above ground. I ADD "T29S R2W" to brass cap aelow the "S2".
A 15" D. Fir bears S.73°30'W., 17.16 ft. (Rec. S.74°W.) Has a healed scar.
A 8" Chinquapin is down, stump bears S.57°30'E., 17.0 ft. (Rec. is S.59°E., 16.5 ft.) Scribing visible on down log "1/4 S"
Placed BT sign on Fir and Chinquapin log.

No new monument set.

New BT - A 16" D. Fir bears S.35°E., 28.7 ft. scribed "1/4 S2 CS BT" on a double blaze. Placed a County BT sign on Fir.

4/13/78

106

Section Corner for Secs. 35 and 36 only of T28-2.

Found - A 1923 US GLO brass cap properly stamped on a 1 1/2" I.P 3" above ground.
A 10" Chinquapin snag bears N.71°W., 11.88 ft. scribing visible, "T28S R2W S35 BT".
A 15" White pine bears N.50°E., 45.54 ft. has a healed blaze.
Placed County BT signs on both trees.

No new monument.

New BT's- A 13" D. Fir bears N.84°E., 30.6 ft. scribed "T28S R2W S36 CS BT' on a double blaze.
A 7" D.Fir bears N.34°30'W.,14.1 ft. scribed "T28S R2W S35 CS Bt" ona double blaze. Placed County BT signs on both trees

Dennis Gaylord, USFS
Deputy, Doug. Co.
Surveyors Office
Roland Simshauser
April 20, 1978
C.S. 59/46