Douglas County Surveyor's Record of Government Corners Renewed

29 T. S. 4 R. W. W. M.

W. F. Briggs. Surveyor
Wit. M. T. Dyer
Thomas Adams.
Mar. 26, 1891
Field Book 96.

F.C. Frear Dep. Co. Sur.
Wit.
Marrison
Safely
H. Wilson
C. J. Wilson
Oct. and Nov. 1918.
M 1-3

Frank Cain Co. Sur.
Witnesses
F. J. Cole
J. T. Black
Wm. Berdine
W. H. Lawrance
May 1915.
Vol 2 Pg. 23

RE-RENEWED, SEE CORNER NO. #262

1/4 SECTION CORNER BETWEEN SECTIONS 20 & 29 — 1
Found no evidence of old corner, so set corner 40.00 chains West of corner common to Sections 20-21-28 &29
SET a post for corner and marked the following tree
Maple 14 Ins. Diam., Bears S 59° 30' E . 28 lks.

1/4 CORNER ON SOUTH SIDE OF SECTION 35. — 2
Renew from old bearing trees. Set in 1½" x 30" Iron Pipe from which
Old Government B.T.s bear as given. Remarked.

SEE CORNER NO. 72

S.E. CORNER OF SECTION NO. 42. Erroneously Entered in Book 4 30-4
Renew from Government B.T.s Set in 1½" x 30" Gal. Iron Pipe and 4" x 48" Fir Stake, from which
A 10" Fir bears S.56°E., 7 lks.
A 10" Fir bears N.88¼°W., 11½ lks.
Should be T. 30-4
S.E. Cor. D.L.C. 30-304

1/4 CORNER NORHT SIDE OF SECTION 2. Erroneously Entered
Renew this corner from my own work. Government set no corner. Set in 1" x 36" Iron pipe, from which
A 8" Fir bears S.45¼°W., 5 lks.
A 20" Fir bears N.45°W., 15 lks.
Should be T. 30-4

S.W. CORNER OF SECTION 36. — COR. 35 | 36 — 3
Renew this corner from old B.T.s. Set in 1" x 36" I. P. and 4" x 48" Cedar Stake, from which
A 12" Fir bears N.13½°E., 20 lks.
A 48" Cedar Bears S.32°W., 9 lks.
SEE C.S. 52/126
5-1963: FOUND 1" I. PIPE AT CORNER - BOTH B.T's.
ADD "BT" IN WOOD TO 48" CEDAR S.32°W. 6.0 ft.
SEE CORNER NO. 218

N.E. CORNER SECTION 2.
Renew this corner from old B.T.s. Set in 1½" x 36" Iron Pipe, from which
A 40" White Oak bears N.46°W., 56½ lks.
A 10" White Oak stump bears S.[illegible]E., 43 lks.
The ¼ Corner on S. side of section 36 bears east 30 lks.
Erroneously Entered in Book 1
Should be T. 30-4
SEE CORNER NO. 4

CORNER TO SECTIONS 4, 5, 8 and 9. — 4
Renew corner from original B.T.s two of which I find standing, that is
A Fir 36" dia. bears S.70°W., 35 lks.
A Fir 10" dia, bears N.52°W., 57 lks.
I marked
A Fir 24" dia. bears N. 8°10'E., 25 lks.
A W. Fir 10" dia. bears N.80°25'W., 70 lks.
A W. Fir 12" dia. bears S. 4°20'E., 27 lks.
SEE CORNER NO. 126 & 29
ALSO # 29

1/4 CORNER BETWEEN 5 and 8. — 5
Renew from stump of original B.T.s. Set post from which
An Alder 27" dia. bears N.88°11'E., 272 lks.
An Alder 6" dia. bears S.78°09'E., 35 lks.
SEE CORNER NO. 77
See C.S. 18/50
1934 Ren.-Boyer

CORNER TO SECTIONS 5, 6, 7 and 8. — 6
Renew from stumps of original witness trees from which
A Fir 37" dia. bears S.34½°W., 151 lks.
A Fir 42" dia. bears N.37°W., 151 lks.
A Fir 18" dia. bears N.39½°E., 36 lks.
A Fir 16" dia. bears S.73°E., 39 lks.
SEE CORNER NO. 182

CORNER OF SECTIONS 4, 5, 32 and 33. (N. BNDRY.) — 7
Renew from original trees two original trees do not check. Set post from which original trees bear as follows
A Fir 20" dia. bears N.70°20'E., 80 lks.
A Fir 20" dia. bears N.82°15'E., 55 lks.
A Fir 42" dia. bears S.72°30'E., 125 lks.
A Fir 24" dia. bears S.17°25'W., 138 lks.
SEE CORNER NO. 186
New Tree
A White Oak 5" dia. bears S.59°W., lks.
N.B. 11/92