Douglas County Surveyor's Record of Government Corners Renewed

T 29 T. S. R 5 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

CONT.

185

We therefore RESET this corner by survey at it's proper proportionate location as follows:

We remove the 1969 monument and set it at the true corner point, extending 6" above ground. We add the markings "Reset 1977" to the brass cap.

At the 1969 corner location, we set a 5/8" x 30" I.Rod with alum. cap attached marked: "Douglas Co. Surveyor 1977".

The 1969 bearing trees are now located as follows:

An 11" D. Fir, condition noted above, bears S.87°E., 40.7 ft.

A 12" D. Fir, condition noted above, bears N.21 1/2°W., 9.7 ft.

A 5/8" I.R. with alum cap attached, marked as noted above, bears N.73°E., 3.89 ft.

A N-W fence bears East approx. 13.5 ft.

Douglas County Surveyors Office
Gary L. Langlitz
Peter L. Earle
Frank Silagy
December 8, 1977
C.S. 59/42

— — — — — — 12/8/77

186

1/4 Corner for Sec. 30 and Sec. 25 of T29-6.

Found - A 1969 County brass cap on a 1" I.P. firmly set, extending 12" above ground properly marked. Ren. #164

A 22" now 24" D. Fir alive with well healed double blaze, bears S.84°E., 5.5 ft. (Rec. per 1969 survey M37-20, S.99°E., 5.5 ft.)

A 12" now 14" D. Fir, alive with well healed double blaze, bears N.83°W., 32.9 ft.

We find no trace of the original corner.

This 1969 corner location is now wrong due to the recent recovery of the original corner common to Sections 19 and 30, T29-5 and Sections 24 and 25, T29-6. We therefore RESET this corner at it's proper proportionate location by survey as follows:

We remove the 1969 monument and set it at the true corner point exten extending 4" above ground. We add the markings "Reset 1977" to the brass cap.

At the 1969 corner location we set a 5/8" x 30" I.R. with alum. cap attached marked "Douglas Co. Surveyor 1977".

The 1969 bearing trees are now located from the 1977 corner as follows:

A 24" D. Fir, condition noted above, bears N.82 1/2°E., 12.8 ft.

A 14" D. Fir condition noted above bears N.77°W., 26.4 ft.

A 5/8" I.Rod with alum. cap attached marked as noted above bears N.74°E., 7.09 ft.

A N-W fence bears East approx 22 ft. A small creek, course N.40°E. bears South, approx. 35 ft.

R. B. Kimberling Doug. Co. Surveyors Off.
F. C. Silagy
December 14, 1977
C.S. 59/42

— — — — — — 12/8/77

187

Section Corner for 18, 19 and Secs. 13 & 24 of T29-6.

Found - A 1" x 27" Iron pipe. Ren. #132 and M 37 - 20

A 12" now 44" B. Oak bears S.85°W., 46.1 ft. (Rec. 56.1 ft.) with a chopped open blaze, 12" center rotted away and another well healed double blaze at the left side of chopping.

A 40" B. Oak bears N.0 1/2°E., 72.8 ft. with scribe marks visible in analmost healed double blaze.

A 48" B. Oak bears N.82°W., 75.0 ft. with a well healed blaze.

A 24" W. Oak bears S.15°E., 134.4 ft. with a well healed blaze.

Set - A 1" x 36" I.P. with brass cap set 6" above ground marked: "Douglas County Surveyor" 1977

I set the I.P. at the N. edge of the brass cap.

R 6 W	T 29 S	
	S 13 / S 24	S 18 / S 19

R 5 W

No new accessories. Corner is at S.W. edge of a 7 ft. high fence post, 8 ft. N.W. of a fence corner to the west and N-S.

— — — — — — 12/14/77

188

North 1/16 for Sec. 19 and Sec. 24 of T29-6

Found - A 1969 County Surveyors brass cap on a 1" x 36" I.P set 14" above ground. Corner was proportioned between the NW cor. Sec. 19 and SW Cor. Sec. 30 and needs resurveyed since the SW cor. Sec. 19 has been found. See M 37 - 20

A 22" White Oak bears N.79°E., 84.2 ft. (Rec. N.80°E., 81.1 ft.) with visible scribing in an almost healed double blaze.

A 30" B. Oak bears S.7°E., 71.4 ft. (Rec. S.4°E., 75.2 ft.) with a well healed double blaze.

CONT. NEXT PAGE