Douglas County Surveyor's Record of Government Corners Renewed

T 29 T.S. R 5 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21281

1/4 Corner for Sectiosn 10 and 15 **228**

Found - 12" now 15" dia. Oak with a fully healed single blaze
We opened and found scribing "S15" bears S.70°E., 119.6 ft.
(distance is good to center of trunk and face of blaze)
No other BTs or monument found. Ren. No's 10 and 87

Set - A 5/8" x 30" long iron rod with a DCSO alum. cap, is set 1" below road surface. Iron rod set at record bearing and dist. to ren. No. 10 southeast BT. (N.70°W., 119.6 ft.)

New Accessories:
A 5/8" x 30" I.R. with a DCSO alum. cap stamped "BO 1 1991" protrudes 2" above ground, bears N.47°E., 53.67 ft.
A found 5/8" I.R. protruding 6" above ground bears S.77½°E., 50.14 ft.
A found 5/8" I.R. protruding 2" above ground bears N.31°W., 35.38 ft.

Douglas County
Surveyors Office
Randall Smith,
Deputy
Terrie Franssen
March 29, 1991
C.S. 64/13

3/29/91

1/4 Corner for Sections 21 and 28 **229**

Found - A 2½" dia. 1962 DCSO brass cap on a 1¼" O.D. iron pipe protruding 14" above ground. Ren. #127
1991 DCSO BC/IP (NW cor. DLC #45 bears East 93.7 ft.)
8" now 6" dia. tipped over dead Oak, no scribing visible bears S.38°E., 73.9 ft. Ren. #29
24" dia. B. Oak now root hole with decayed wood, bears N.41°W., 22.7 ft. Ren. No. 29
10" now 17" dia. W. Oak with a fully healed double blaze bears S.23 3/4°W., 30.4 ft. (agrees with Ren. #5 Wenderoth 1944), J. Powell rec. of S.20°W., 33.0 ft., is the rec. of an orig. BT)
18" now 33" shell of a burnt out 2 ft. high oak, bears N.63°E., 24.4 ft. (Rec. N.59°E., 24.4 ft.) Orig. BT
6" now 10" dia. madrone with a fully healed double blaze bears N.23°W., 53.6 ft. (Rec. N.20°W., 53.6 ft.) Ren. No. 127
6" now 10" dia. madrone with a partially healed double blaze scribing visible "S28 CS BT" bears S.49½°E., 10.4 ft. (agrees with rec.) Ren. No. 159

New BT - 8" dia. madrone double blazed and scribed "1/4 S21 CS BT" bears N.7°E., 8.6 ft.

Douglas County
Surveyors Office
Randall Smith
Terrie Franssen
April 12, 1991
C.S. 64/13

4/12/91

Northwest Corner for DLS #45 **230**

Found - 3/4" threaded iron rod with bolt, prtrudes 2" above ground. #78
30" now 30" dia. W. Oak with a fully healed double blaze bears N.6¼°E., 44.5 ft. (Rec. N.8°E., 44.5 ft.) Ren. NO. 78
24" now 30" dia. W. Oak with a fully healed double blaze bears N.84°E., 73.0 ft. (Rec. N.84°E., 83.0 ft., probable chaining error) Ren. #78

Set - 3/4" iron rod is referenced and removed. A 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. x 32" long iron pipe is set at referenced position. BC/IP now protrudes 5" above ground. 3/4" I.R. measures 40" long and is set along north edge of BC/IP protruding 5" above ground. Cap is marked:
Douglas County Surveyors
T29S
NW Cor | DLC 45 | R 5 W
1991
Office

1962 DCSO BC/IP (T29S R5W S¼ Sec. 21) bears west,93.7 ft. (agrees with record.

New BTs- 7" dia. madrone double blazed and scribed "NW DLC 45 CS BT" bears S.34°E., 16.4 ft.
9" dia. madrone double blazed and scribed "NW DLC 45 CS BT" bears S.45°W., 12.2 ft.

Douglas County
Surveyors Office
Randall Smith, Deputy
Terrie Franssen
April 12, 1991
C. S. 64/13

4/12/91