Douglas County Surveyor's Record of Government Corners Renewed

T 29 T.S. R 8 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

171

S 1/16 Sec. 13

Found - a 2 1/2" Iron pipe firmly set, extending 8" above ground, with standard BLM brass cap attached mkd: S 1/16 C C S 13 1975
(See unofficial BLM survey in C.S. 58/82)

A 10" D. Fir with scribing "C S1/16 S13 BT" visible on unhealed single blaze bears S.78°W., 32.3 ft. (Rec. per CS 58/82 S.80°W., 32.3 ft.)

A 12" now 13" D. Fir, with scribing "C S 1/16 S13 BT" visible on unhealed single blaze bears N.17°E., 23.1 ft. (Rec. per C.S. File 58/82, N.15°E., 23.1 ft.)

DID NOT REMONUMENT CORNER.

Gary L. Langlitz
Peter L. Earle
Stephen J. Flause
Doug. Co. Surveyors Office
May 9, 1977
C.S. 59/34

5/9/77

172

S W 1/16 Corner for Sec. 13.

Found - A 2 1/2" Iron pipe firmly set, extending 8" above ground with standard BLM brass cap attached mkd. S W 1/16 S13 1975
(See C.S. 58/82 for unofficial BLM survey)

A 16" D. Fir alive with scribing "SW 1/16 S 13 BT" visible on unhealed single blaze, bears S.81°W., 21.1 ft.

A 6" now 8" Incense Cedar, alive with scribing "SW 1/16 S 13 BT" visible on unhealed single blaze, bears N.22°E., 23.1 ft. (Rec. per C.S- 58-82 N.25°E., 23.1 ft.).

WE DO NOT REMONUMENT.

5/9/77

173

Center North 1/16 for Sec. 31.

Found - 1965 BLM brass cap properly marked 6" above ground. Pipe was not bent but 30° from vertical anc brass cap fastening bolt was broken.

A 11" W. Oak bears N.30°E., 25.7 ft. with a rotted out blaze.

A 14" Fir snag, 35 ft. tall bears S.75 3/4°W., 28.0 ft. with scribing "CN 1/16 S31 BT" in single unhealed blaze.

Set - Secured brass cap on iron pipe and reset from bearing trees 5" above ground and stamped to read "T29S R8W" N 1/16 C C S31 Reset 1977

New BT - A 8" Cedar bears S.6°E., 22.9 ft. double blazed and scribed "CN 1/16 S31 CS BT".

R. B. Kimberling
M. W. Cline
For: Doug. Co. Surveyors Office
Oct. 10, 1977
C.S. 59/40

10/10/77

174

West 1/16 Corner for Secs. 12 and 13.

Corner determined by single proportion measurement.

Set - A 3/4" x 24" I.P. with Iron rod protruding from bottom and a brass cap attached on top. Cap stamped: "Douglas County Surveyor"
T 29 S R 8 W
W 1/16 S 12 / S 13
1977

BT's- A 14" D. Fir bears S.68 1/2°E., 20.0 ft. Tree scribed "W 1/16 S13 CS BT" on a double blaze.

A 16" D. Fir bears N.44°E., 21.7 ft. Tree scribed "W 1/16 S12 CS BT" on a double blaze.

Corner lies on SE slope.

Gary Langlitz
Larry Monrean
P. L. Earle
S. J. Flause
Dougl. Co. Surveyors Office
ct. 1977
.S. 59/40

10/17/77

JAN 78

175

1/4 Corner for Secs. 9 and 10.

Found - A 1/2" I.R. and a 1967 County brass cap. Ren. #27 and #133 .

An orig. 20" now 40" Fir, down and rotten with scribing "1/4 S9 BT" visible on unhealed blaze, bears N. 1/2°E., 57.4 ft.

An orig. 50" now 60" D. Fir, down, no marks visible, bears N. 1/2°W., 35.0 ft.

A 30" now 36" Hemlock, alive with well-healed double blaze bears N.70 1/2°W., 55.7 ft.

A 48" D. Fir with bark scribing "1/4 S10 CS BT" visible on double blaze, bears S.44°E., 39.4 ft. (Rec. S.46°E. 37.6 ft. dist. is good to face).

A 15" now 18" R. Cedar with scribing "4S1C" visible on partially healed double blaze, bears S.37°E., 11.4 ft.

No new monument set.

New BT - A 12" I. Cedar, scribed "1/4 S10 CS BT" on a double blaze, N.55°E., 143.7 ft. Note: the fir & cedar BT's in the SE quad. will be cut in the near future during clearing for a new power line.

Gary Langlitz
Frank C. Silagy
Doug. Co. Surveyors Office
March 20, 1978
C.S. 59/46

CORNER REPORT 9/26/86
O.S.H.D. 7/3/86
C.S. 63/9