Douglas County Surveyor's Record of Government Corners Renewed

30 T. S. 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

150

1/4 Corner for Sec. 12 only. East side (See Ren. #92)
Note: This corner is located along the Willamette Meridian as surveyed in 1857 and later changed.
Found - A stone, 24"x8"x6", firmly set, extending 8" above ground and leaning westerly, with faint "1/4" chiseled on west face.
From which:
An orig. 1857 BT, a 15" now 34" D. Fir, alive with well healed blaze, bears N.10°W., 6.1 ft. (Rec. N.10°W., 5.2 ft.)
An orig. 1857 BT, a 9" now 14" I. Cedar, alive with "BT" visible on unhealed blaze bears S.40°E., 7.1 ft. (Rec. S.40°E 6.6 ft.) Note: The markings on this tree were partially obliterated during the 1923 retracement survey.
A 1923 BT, a 12" now 20" I. Cedar bears S.35°W., 8.8 ft. (Rec. S.35°W., 9.9 ft.) Alive and well healed. Note: the orig. measurement fits this BT at breast height, not at ground level.
At the corner point, we set:
A 1" x 30" I. P.- 24" in the ground with the orig. stone along the west side, stamped:

Douglas County Surveyor
1976

T 30 S R 1 W
1/4 S 12

9/16/76

Gary L. Langlitz, Co. Surveyors Office
Mike Tompkins
Sept. 16, 1976
C.S. 59/24

151

1/4 Corner for Secs. 14 and 15.
Found - A 14"x11"x6" stone (Rec. 12"x8"x6")
From which: Ren. #3
A 42" Pine stump bears S.83°E., 107.5 ft. Shows fragmentary scribing, a pronounced "BT".
A down 30" Cedar, bears N.89 1/2°W., 149.2 ft. Shows "1/4 BT" in a double blaze.
No sign of orig. BT's or corner post.
Set - A 1"x30" I. Pipe with brass cap stamped:

Douglas Co. Surveyor
1976

T 30 S R 1 W
S 15 | S 14
1/4

Set - Found stone on north side of cap.
New BT's - A 6" D. Fir, bears N.36°W., 8.0 ft. mkd. "1/4 S15 CS BT".
A 5" D.Fir, bears S.67°E., 13.9 ft. mkd. "1/4 S14 CS BT".
9/27/76

#176
RE-RENEWED, SEE CORNER NO.

A. Victor Cangie, Doug. Co. Surveyors Office
Mike L. Tompkins
Sept. 27, 1976
C.S. 59/24

152

1/4 Corner for Secs. 11 and 14.
Found - An orig. 40" now 48" Pine stump with previously opened double blazes. Find fragmentary scribing on top blaze & "BT" showing on bottom. Blaze does not face corner.
An 18" Oak, previously opened. Could find no sign of scribing.
No evidence of orig. corner post.
Given the bearings and distances from above Pine stump and 18" Oak, an intersecting point is impossible. I discount the Oak as a BT and set corner off of orig. Pine stump. It bears S.14°E., 21.8 ft.
Set - A 1" x 30" I. Pipe with brass cap stamped:

Douglas Co. Surveyor
1976

T 30 S R 1 W
S 11 1/4
S 14

New BT's - A 36" B. Oak, bears S.3°W., 46.2 ft. mkd. "1/4 S14 CS BT".
A 14" D.Fir bears N.32°E., 11.2 ft. mkd. "1/4 S11 CS BT".
9/27/76

#169
RE-RENEWED, SEE CORNER NO.

3/77

153

1/4 Corner for Secs. 22 and 23.
Found - 1923 GLO brass cap mkd. 1/4 S22 S23, Township and range not stamped on brass cap. (T30S R1W). Brass cap 24" above ground and leaning toward center of decomposed stump, all that remains of the orig. corner tree.
A Fir tree bears S.82°E., 57.42 ft. & is blown down. Has healed blaze.
A Fir bears S.35°W., 20.46 ft. and is blown down. Has healed blaze.
Renewal: I remove brass cap & I.P. (which is loose) & place in exact center of the decomposed remains of the orig. corner tree. Top of brass cap is set flush with ground.
New BT's-A 6" W. Fir bears N.59°30'E., 27.3 ft. scribed "1/4 S23 CS BT" on a double blaze.
A 6" W. Fir bears S.34°30'W., 16.6 ft. scribed "1/4 S22 CS BT" on a double blaze.
Note: Corner lies on a North slope, South of Jackson Creek in a recently logged area.

Dennis Gaylord, U.S. Forest Serv.
Deputy, Doug. Co. Surveyors
Walter Barton, Witness
March 17, 1977
C.S. 59/31