Douglas County Surveyor's Record of Government Corners Renewed

T 30 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

298

Doug. Co. Surveyors Office
Karen Reed
P. Earle; F. Silagy
Vicki Woodral
July 18, 1979
RM 3 - 26
C.S. 61/3

N 1/16 For Secs. 31 and 32.
Found - A 2" I.P. 1" above ground set by Wenderoth in 1946. Said pipe bears S.70°13'13"E., 99.54 ft. dist. from new position of N 1/16.
A 9" B. Oak bears N.40°W., 13.0 ft. (Rec. N.38°46'W., 12.7 ft.) with healed over blaze. (M20-24)
A 10" B. Oak, now 22" bears S.88°E., 46.5 ft. (Rec. S.83°36'E., 46.0 ft.) with healed over blaze. (M20-24)
Iron pipe and trees left intact. This corner set in wrong position. Our survey of the area determined that surrounding corners are in wrong positions therefore correction of these corners sets new position for N. 1/16.
Set - A 1" x 36" I.P. with brass cap marked "Douglas County Surveyor T30S R5W N 1/16 S31 S32 1979"
New BT's- A 22" B. Oak scribed "N 1/16 S31 CS BT" in a double blaze bear S.52°E., 17.6 ft.
A 10" Fir scribed "N 1/16 S32 CS BT" in a double blaze bears S.47°W., 15.2 ft.

7/18/79

299

Doug. Co. Surveyors Office
Stephen J. Flause
Terrie Plouff
Shawn Means
April 1980
C.S. 61/6

1/4 Corner for Secs. 11 and 14 See Ren. #138 & #182
Found - A 6" now a 13" B. Oak bears N.7°E., 69.3 ft. (Rec. N.7°W., 69.0 ft. corrected in Ren. #182 to N.7°E., 69.0 ft. recorded in B.L.M. survey as N.8 1/4°E., 69.3 ft.) with healed double blaze no scribing visible.
A 5" now a 9" W. Oak bears N.26°E., 61.8 ft. per Ren. #138 has healed double blaze no scribing visible.
A 24" now a 31" Madrone bears N.51°W., 72.5 ft. (Rec. 75.0 ft. which appears to be a slope measurement). B.L.M. record N.51 3/4°W., 71.9 ft. Tree has healed double blaze no scribing visible.
Set - A 1" x 30" iron pipe with brass cap properly stamped and protruding 0.1 ft. from surface.
Note: This corner was set previously by B.L.M. resurvey in 1969. No monument was found, appears to have been removed as we find a depression in soil marked with stake and flagging.
Corner was renewed from checking bearings and distances from stake found in depression.
No other trees available, existing trees are retagged as recorded.

4/28/80

300

William J. Ruppert
LS #866
For: Darrel Green
May 1980
M 83 - 65 A&B

1/4 Corner for Section 6 and Section 31, T.29S. R.5W.
Fd - 1/2" x 48" Iron pipe. See Ren. #12 T.29-5
36" W. Oak bears N.40°30'E., 63.5 ft. with good scar now dead.
30" W. Oak bears S.72°16'E., 33.5 ft.
Set - A 1" x 30" galvanized iron pipe with 2 1/2" brass cap at position of 1/2" pipe mkd: T29S \| S31 / T30S \| S6 1/4 R5W PLS 866 1980
Replaced 1/2" pipe along east side of brass cap.
New BT- 16" W. Oak bears N.44°50'W., 95.65 ft. scribed "1/4 S31 BT".
Attached brass washer LS#866 to lower blaze.

FD. B.C. 9/91 #1991-0071 R. BROWN

6/5/80

301

John H. Markham, Jr.
L.S. 1261
For: Strobridge, Wm.
May 24, 1982
M 92 - 33
cs 58/229

1/4 Corner for Secs. 19 & 30.
Set - 1-1/4" x 36" galv. pipe w/ B.C. at prop. meas., mkd: L.S. 1261 1/4 S.19 S.30 1982.
New BTs- 18" maple bears S.22°E.,4.0-ft.
24" fir bears N.25°E.,38.3-ft.

5/24/82

302

John H. Markham, Jr.
L.S. 1261
For: Glenn Hills Subdivision
Oct. 20, 1982
C.S. 58/229

Center 1/4 Corner for Section 30
Set - 1 1/2" x 36" galv. pipe with brass cap mkd. LS 1261 C 1/4 S30 1982.
From which:
A 14" pine bears due West 272.0 ft. mkd. C 1/4 S30 BT
A 30" W. Oak bears N.70°E., 213.6 ft. mkd. C 1/4 S30 BT.

10/20/82