Douglas County Surveyor's Record of Government Corners Renewed

30 T.S. 8 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31891

12

Section Corner to Sections 27, 28, 33, & 34. #119

Found - Three Orig. BT'S:

Orig. 17", now 20" R.Fir S. 6°W. 13.2 ft. Good bark scribing T30S R8W S33 BT.

Orig. 22", now 30" R.Fir N.41°E. 4.6 ft. Good bark scribing T30S R8W S27 BT.

Orig. 34", now 40" R.Fir N.40°W. 31.0 ft. Good bark scribing T30S.

No Trace of Orig. S. E. BT.

Set Brass Cap at Corner Mkd: T30S R8W S28|S27 / S33|S34 County Surveyor's Office, 1958.

New BT's: 5" Cedar bears S.87°E. 23.0 ft. scribed S34 CS BT.

12" W. Fir bears N.26½°W. 50.8 ft. scribed S28 T30S R8W CS BT.

10" W.Fir bears N.48°E. 69.5 ft. scribed S27 T30S R8W CS BT.

RE-RENEWED CORNER NO.

- - - - - - - - - - - - - -

13

¼ Section Corner to Sections 25 & 26.

Found - Steel Fence Post at Cor. & Both Orig. BT's:

Orig. 36", now 48" Fir S.23°E. 21.1 ft. Faint bark Scribe mks"¼S".

Orig. 30", now 42" Fir S.64°W. 11.9 ft. Faint bark Scribe "¼S".

I do not set Brass Cap at Corner.

New BT's: 8" R.Fir bears S.72½°E. 45.0 ft. scribed ¼ S25 CS BT.

I rescribe, bark, 42" R.Fir S.64°W. 13.5 ft. ¼ S26 CS BT.

- - - - - - - - - - - - - -

14

Section Corner to Sections 9, 10, 15, & 16. SAME AS #10

Found - All Orig. BT's:

Orig. 16", now 36" Cedar N.28°W. 31.7 ft. Shows faint scribe mks.

Orig. 15", now 36" Fir Stump N.28°E. 15.2 ft. I do not open, good scar at base.

Orig. 46", now 48" Fir S.36°W. 34.9 ft. Shows good bark scribing.

Orig. 16", now 36" Fir S.76°E. 11.2 ft. Shows good bark scribing.

Set Brass Cap at Corner Mkd: S 9|S10 / S16|S15 T30S R8W County Surveyor's Office, 1958

New BT's: 10" W. Fir bears S.88½°W. 35.1 ft. scribed S16 T30S R8W CS BT.

Rescribe Orig, now 36" Cedar N.28°W. 31.7 ft. S9 T30S R8W CS BT.

10" R,Fir bears S.18½°E. 49.5 ft. scribed S15 T30S R8W CS BT.

8" R.Fir bears N.13°E. 32.8 ft. scribed S10 T30S R8W CS BT.

James W. Byron, Deputy
M. Godfrey
S. A. Bilow
August, 1958
C. S. File No. 49/108

15

¼ Section Corner to Sections 15 & 16.

Found - Laurel Tree, now 22" diam, S.44°W. 40.3 ft. Upper blaze previously chopped open & face rotted, chopped out lower blaze & found portions of scribe Mks. on rotted face.

Dead Laurel Tree, now 9" diam, N.55°E. instead of N.65°E. 31.7 ft. Upper blaze previously chopped open & face rotted. Chopped out lower blaze & found portions of scribe Mks. on rotted face.

At Corner Set Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1958 T30S R8W ¼ S16/S15 - Erect Mound of Stones.

Blaze & Scribe: 15" D.Fir N.82½°E. 24 ft. Mkd. ¼ S15 CS BT.

15" D.Fir S.49°W. 30.7 ft. Mkd. ¼ S16 CS BT.

- - - - - - - - - - - - - -

16

¼ Section Corner to Sections 22 & 27.

Found - Cedar Tree, now 13" diam., S.32°E. 5.3 ft. This tree has been chopped open several years ago & scar has not completely covered portions of scribing in very good condition. Can be seen. Did not rescribe tree.

Fir Tree, now 24" diam, North 29.7 ft. Upper Scar has been opened previously, & good scribing "¼S", can be plainly seen on old face. Did not rescribe Tree.

At Corner set Iron Pipe with Brass Cap mkd: County Surveyor's Office, 1958, T30S R8W ¼ S22/S27

RE-RENEWED CORNER NO. 44

- - - - - - - - - - - - - -

James W. Byron, Deputy Surveyor
Milo Godfrey
S. A. Bilow
Sept. 1958
C. S. File No. 49/108