Douglas County Surveyor's Record of Government Corners Renewed

T 30 T. S. R 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

129

1/4 Corner for Sections 3 and 10
Found no evidence of original corner.
Set - 5/8" x 36" Iron rod with aluminum cap marked LS 498
BTs - 11" fir, N.58°E., 12.1 ft.
7" fir, S.64°W., 44.1 ft.

8/82

130

1/4 Corner for Sections 10 and 11
Found - 1" iron pipe. Ren. #17
50" fir stump, N.42°E., 71.9 ft. Scribe visible.
11" fir, S.10°E., 13.5 ft. healed.
21" fir, N.15 1/2°W., 86.5 ft. Healed
New BT - 11" fir, N.49°W., 19.1 ft.

193

131

1/4 Corner for Secs. 9 and 10.
Found - 46" fir stump, S.65°E., 14.2 ft. (Rec. 12.5 ft.) Old axe marks.
27" fir stub, S.53°W., 21.9 ft. (21.1 ft.) Old cruiser mark
Record distances fit to face of Orig. diameter. Corner fits creek call and ridge call to the south.
Set - 5/8" x 36" Iron rod and aluminum cap marked "LS 498".
New BTs - 6" fir, East 65.8 ft.
15" cedar, N.37°W., 62.0 ft.

132

Section corner for Secs. 9, 10, 15 and 16.
Found - 1964 County brass cap and iron pipe. Ren. #43
17" cedar, S.20°E., 21.9 ft. scribe visible.
21" fir, S.50°W., 3.5 ft. Down on face.
New BTs - 12" fir, N.68°E., 31.0 ft.
10" fir, N.21°W., 26.2 ft.
6" cedar, S.46°W., 11.1 ft.

See 2004/2005 BLM Resurvey Pg 21271-2

Pool By Carl Sweedon 11/2007 M154-67

133

1/4 Corner for Secs. 9 and 16.
Found - 1964 County brass cap and iron pipe. Ren. #37
18" fir, N.2°E., 13.2 ft. burnt face. (Record N.2°W.)
11" fir, N.51°E., 28.3 ft. Healed.
New BT - Scribed 10" madrone, S.52°W., 15.4 ft.

See 2004/2005 BLM Resurvey Pg. 21273

134

Section Corner for Secs. 25 and 36; and Secs. 30 and 31 of T.30-8
Found - 1" x 30" Iron pipe with properly marked 1968 County brass cap attached, standing loosely approx. 4" in the ground. Ren. #97
Orig. 15" now 28" fir bears N.43°W., 24.4 ft. (Rec. N.47°W.) with pitched over previously opened blaze.
Orig. 30" now 54" fir with scribed "BT" in previously opened blaze alive. Did not take bearing & dist. since it would have required cutting many trees out of line of sight and I had 6 other BTs close to corner.
Orig. 15" now 32" pine with pitched over previously opened blaze bears N.28°E., 57.4 ft. (Rec. N.25°E.)
9" fir now 10" with well healed single blaze bears S.52°E., 16.2 ft
11" W. oak with scribed "S R8W S30 CS BT" in partially healed blaze bears N.65°E., 33.6 ft. (REc. 34.2 ft.) Ren. #97
8" now 9" W. oak with scribed "T30S R9W S25 CS BT" bears N.10°W., 30.0 ft.
8" now 10" fir with well healed single blaze bears S.82°W., 26.6 ft
Root hole and rotted remains of possible orig. 5" oak with no scribing or face visible. Root hole bears S.22°E., 6.4 ft. (Rec. S.10°E., 5.9 ft.)
Set - Since the location I found the brass cap at, fit all the trees well I reference its location and reset the pipe 24" into the ground and add the marks "Reset 1982" to the cap.
Blaze line runs north from corner to road 30-9-24.1

12/13/82

Howard Johnstone L.S. #498
For: Roseburg Lumber Company
August 1982
M 90 - 26

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
John Powell
Randy Smith
Dec. 13, 1982
C.S. 62/1