Douglas County Surveyor's Record of Government Corners Renewed

T. 31 S. T.S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

184

¼ Corner to Sections 26 and 25.
Found - Stone at ¼ Corner, "¼" West Face.
12" Fir, now rotten Stump, S. 78° W. 14.5 ft.
11" Fir, now 14", S. 12½°E. 12.5 ft. Has been opened for scribe. Face rotten but faint scribe marks visible.
Set - Brass Cap at ¼ Cor.Mkd: County Surveyor's Office, 1966 T31S R3W ¼ S 26/S 25
New BT's: 13" Hemlock N. 40° E. 23.0 ft. scribed ¼ S25 CS BT.
25" D. Fir N. 31° W. 6.2 ft. scribed ¼ S26 CS BT.

- - - - - - - - - - - - - -

185

¼ Corner to Sections 25 and 36.
Found - 12 x 12 x 12" Stone Mkd: "¼" North Face.
6" Hemlock, now 8", S. 10½°W. 7.9 ft., scribe visible "¼S".
No trace of 11" Fir N.29½°W. 21.1 ft.
Set - Brass Cap at ¼ Cor. Mkd: County Surveyor's Office, 1966 T31S R3W ¼ S 25 / S 36
New BT: 7" Yew Wood N. 19° W. 37.2 ft. scribed ¼ S25 CS BT.
Note - This corner lies west of creek 22.0 ft.

FD. oK 3/91 M 111 67

John M. Powell
Frank Jones & Joe Brady
April 1966
C. S. File No. 52/63

- - - - - - - - - -

186

Corner to Sections 30 and 31 only, T31-2W.
Found - Stone at Sec. Cor. Mkd: C. C. on East Face.
36" D. Fir, now 40", N. 40° E. 11.2 ft., shows good scar.
12" D. Fir, now Snag, S. 48° E. 23.8 ft., opened for scrbng. (This bearing S.B. S.40°E.)
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1966 — R 3 W | T 31 S | S 30 / S 31 | R 2 W
New BT: 24" D. Fir S. 10° W. 34.0 ft. scribed T31S R3W S25 CS BT.

- - - - - - - - - - - - -

187

Sec. Corner to Secs. 25 & 36, T31-3W.
Found - 30" Fir N. 35° W. 28.0 ft., shows scribe marks.
16" Fir, now down, N. 45° E. 1.0 ft.
No trace of Iron Pipe, See Ren. #35.
Orig. 30" Fir, now stump, S. 18° W. 53.0 ft.
Orig. 30" Fir, now down, S. 30° E. 23.0 ft., shows scar.
Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office 1966 — R 3 W | T 31 S | S 25 / S 36 | R 2 W
New BT: 8" Chinquapin S. 60° W. 31.3 ft. scribed T31S R3W S36 CS BT.

- - - - - - - - - - - - - - - - - - -

188

¼ Corner to Section 25 only, T31-3W.
Found - 18x8x5 Ironstone at ¼ Corner.
10" Yew, now 14", N. 17½° W. 13.9 ft., found two old, rotten faces, but no scribe marks visible.
6" Hemlock S.73°W., No trace of this tree.
Good call on creek. 78.5 ft. (119 chs.) from creek.
Set - Brass Cap at ¼ Cor. Mkd: County Surveyor's Office, 1966 — R 3W ¼ T 31 S S 25 R 2W
New BT's: 6" Hemlock N. 57½° W. 30.3 ft. mkd. ¼ S25 CS BT.
15" Yew S. 23° W. 23.4 ft. mkd. ¼ S25 CS BT.

John M. Powell & Crew
C.S. File No. 54/28

August 5, 1966

- - - - - - - - -

189

S. E. Corner Section 36 only, T31-3W.
Found - ¾" I. Pipe, bent over under small log, See Ren. #41.
40" W. Fir N. 55° W. 60.5 ft., shows good scar.
11", now 14" Cedar, N. 40° E. 68.5 ft., scribe visible "S1 BT".
15", W. Fir, now stump, S. 16° W. 28.4 ft., opened for scribe "T32".
24" D. Fir, now down, S. 14° E. 7.9 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1966 — T 31 S | S 36 | R 3W | S 1 | T 32 S
Reblazed & Rescribed:
14" Cedar N. 40° E. 68.5 ft. scribed T32S R3W S 1 CS BT.
No other trees available. This corner lies just on S. side of small ridge.

RE-RENEWED SEE CORNER NO #232

Aug. 30, 1966

- - - - - - - -