Douglas County Surveyor's Record of Government Corners Renewed

T 31 T.S. R 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21091

236

Section Corner for Secs. 18, 19 and Secs. 13 and 24 of T.31-4
Found - 32" Fir, N.46°W., 15.3 ft. (Orig.)
14" Fir, N.62°E., 22.0 ft. See Ren. #59 in T.31-4
14" Fir, N.24°E., 3.6 ft. Down. (Orig.)
25" Fir, S.58 1/2°E., 43.6 ft. (Orig.)
Set - 5/8" x 40" I.R. and Alum. Cap.
New BT's- 14" Fir, S.42°W., 58.3 ft.
25" Fir, S.74°E., 39.7 ft.

237

1/4 Corner for Secs. 18 and 17
Found - 40" Fir, West 29.7 ft.
16" Maple, S.56°E., 19.8 ft.
Set - 5/8" x 30" I.R. and Alum. cap.
New BT's- 6" Hemlock, S.68°E., 20.8 ft.
5" Hemlock, S.74°W., 6.2 ft.

238

Howard Johnstone
For: Roseburg Lumber Company
Dec. 17, 1980
M 86 - 42

Section corner for Secs. 17, 18, 19 and 20
Found - 10" Rotten Madrone stump - scribed, bears N.52°E., 36.6 ft. (Rec. N.45 1/2°E.)
18" Madrone, S.13°E., 7.3 ft. (Rec. S.19°E.)
Set - 5/8" x 30" I.R. and Alum. cap.
New BT's- 12" Madrone, N.12°W., 48.6 ft.
22" Fir, N.70°E., 15.0 ft.
15" Fir, S.81°E., 22.0 ft.
8" Fir, S.63°W., 28.0 ft.
Note - Markham's 1 1/4" I.P. bears S.5°24'34"W., 121.97 ft. Ren. #66

239

1/4 Corner for Secs. 17 and 20
Set - 5/8" x 30" I.R. and alum. cap
BT's- 8" Fir. S.73°W., 10.8 ft.
6" Fir, N.21°E., 7.0 ft.
Note - Markham's 1 1/4" I.P. bears S.67°07'16"W., 111.22 ft. Ren. #64

12/17/80

240

Gregory Quibell
Deputy, Doug. Co. Surveyors Office
Debbie Stewart
April 23, 1981
C.S. 61/19

1/4 Corner for Secs. 23 and 26
Found - Orig. 20" x 12" x 8" stone 15" in the ground with a faint 1/4 on north face.
6" now 24" fir with well healed blaze bears N.46°W., (rec. N.41 1/2°W.) 14.2 ft.
6" now 14" yew with partial scribe visible in partially healed blaze bears S.53°E., (Rec. S.50°E) 5.6 ft.
Set - At the location of orig. stone, I SET a brass cap marked "Douglas County Surveyor S23 S26 T31S R3W 1981"
Original stone was placed along southerly side of brass cap.
New BT's -16" fir bears S.52°W., 12.9 ft. marked 1/4 S26 CS BT in double blaze.
8" fir bears N.6°E., 2.7 ft. marked 1/4 S23 CS BT in double blaze.

4/23/81

241

Gregory Quibell,
Deputy, Doug. Co. Surveyors Office
Debbie Stewart
April 27, 1981
C.S. 61/19

1/4 Corner for Sec. 18; and Sec. 13 of T.31-4
Found - 1 1/2" x 30" pipe firmly set. Ren. #81 in T.31-4
Orig. 34" now 40" fir with BLM BT tag & well healed blze lying downhill approx. 30 ft. from its orig. location. Remains of stump hole & root bears S.66°E., 33.0 ft.
Orig. 18" now 35" fir with well healed blaze, BLM tag & large "X" in bark bears S.48°W., 17.4 ft.
8" now 9" fir with well healed blaze bears S.20°W., 24.8 ft. (Rec. 26.0 ft.) Ren. #81, T.31-4
11" now 12" fir with well healed blaze bears N.29°E., 24.0 ft. #81
Remains of 7" fir scribed 1/4 S18 BT visible. Tree is down & rotten Exact orig. location of tree is not apparent. Ren. 81
New BT's -9" madrone scribed 1/4 S18 CS BT in double blaze bears N.51°E., 42.3 ft.
13" yew scribed 1/4 S13 CS BT in double blaze bears N.14°W., 36.0ft