Douglas County Surveyor's Record of Government Corners Renewed

T. 31 W. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

245

(Cont.)

BTs - The 26-1/2" Cedar, a snag during Ren.# 105, is now down with some scribe marks visible on unhealed face. The Rec. brng, & dist.(S.12-1/4°W.,21.8-ft.) falls on the root wad of the BT.

FD OK BY R. BROWN 4-93 M112-72

A Fir 18" now a stump (size indeterminate) with fragmentary scribing visible bears S.22°E., 48.0-ft. (Rec.S.19°12'E.47.5-ft.) #19.

A D. Fir 19" now 21" with well healed dble.blaze, bears S.16°E., 80.1-ft.

A D. Fir 8" now 14" with well healed dble. blaze bears S.86°W., 17.2-ft. (Rec. S.83°W.,17.5-ft.).

A not of record D. Fir, 22" dia., bears North 23.9-ft. has a yellow tag marked "31S 3W KB 8/20/39".

Set - The found monument is set at position as determined by the previous note.

Note - For sketch, see C.S. 61/30. - - - - 12/30/81

Larry E. Monrean
Deputy Douglas County
Surveyors Office
J.M. Powell, witness
Dec. 30, 1981
C.S. 61/30

246

1/4 Corner for Secs. 30 and 31
CONDITION REPORT ONLY

Found - Original monument not found.

Note: Inspection of the map in Co. Surveyors file M 27 - 14 showing the method by which the following monuments were set indicates that the proportioning procedure as defined by the BLM Surveying Manual was not used. The monuments are not at the most probable position of the quarter corner. Due to their long standing and use in the area it is necessary to leave the evidence found for future survey needs.

Found - a 1" diam. iron pipe. Ren. #20

A 1" diam. Iron pipe with an attached brass cap, 1966 County cap properly marked. Ren. #153 Iron pipe is along westerly side of brass cap monument.

A madrone 12" now 14" with well healed double blaze bears S.41°E., 23.8 ft. (Rec. S.38 1/2°E., 28.8 ft.) (Tag on tree notes distance as 123.8 ft.)

A D. fir, 13" now 15" with well healed double blaze bears N.37 1/2°E., 65.0 ft. (Rec. N.35°E.)

- - - - - - 12/29/81

Larry E. Monrean
Doug. Co. Surveyors
Office
John Powell
Jim Buley
Dec. 29-30/1981
C.S. 61/30

247

1/4 Corner for Sec. 31; and Sec. 36 of T.31-4

FD OK BY R. BROWN 4-93 M112-72

Found - Original post not found.

1" diam. Iron pipe with 1957 County brass cap attached properly marked. Monument is firmly set 10" above ground. Ren. #38

Orig. 16" fir now a stump 28" diam. with fragmentary scribing visible bears N.50°E., 20.5 ft. to face.

An 18" orig. fir now a stump 28" diam. with scribing "1/4 S" visible bears S.43°W 12.5 ft. to face (Rec. S.32°W.)

A W. fir, 16" now 18" with well healed double blaze bears N.21°E., 79.5 ft. Ren. #38

A W. fir 12" now 18" with well healed double blaze bears N.83 1/2°W., 53.2 ft. Ren. #38

New BTs- A 21" D. fir sceibed "1/4 S36 CS BT" on a double blaze bears N.10°W., 74.8 ft.

A 10" W. fir scribed "1/4 S31 CS BT" on a double blaze bears S.43°E., 15.1 ft. to bottom of lower blaze.

Sketch in C.S. file.

- - - - - - - - - 12/30/81

248

Howard Johnstone
L.S. 498
For: Roseburg Lmbr. Co.
June 10, 1982
M 92 - 44

Sec. corner common to Secs. 4,5,8, & 9.

Fd. - 1966 County I.P. w/ B.C. Ren.#142

BTs - 52" fir bears S.30°E.,33.3-ft. bark scribed.
36" cedar bears N.17°W.,41.0-ft. scar.
8" laurel bears N.87°W.,8.8-ft. stump hole.

New BTs- 10" hemlock bears N.80°E.,35.7-ft. - - - 6/10/82

249

North 1/4 Cor. of Sec. 4, only.

Set - 5/8" x 36" I.R. and aluminum cap mkd. LS 498.

New BTs- 25" fir bears N.8°W.,5.4-ft.
7" fir bears S.64°W.,9.5-ft. - - - - 6/10/82

250

1/4 Corner common to Secs. 4, & 9.

Fd. - 5" x 6" x 10" Stone marked "1/4".

BTs - 10" madrone bears S.10-3/4°W.,23.6-ft. Rotten face, partial scribe
14" fir bears N.68-1/4°W.,11.2-ft. healed.

CONTINUED OVER