Douglas County Surveyor's Record of Government Corners Renewed

T. 31 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

CONTINUED :

250

1/4 Cor. common to Secs. 4, & 9.
Set - 5/8" x 36" I.R. and alum. cap mkd. LS 498.
New BTs- 34" fir bears S.76°E.,29.3-ft.
23" fir bears N.16°W.,15.5-ft. 6/10/82

Howard Johnstone
L.S. 498
For: Rsbg. Lmbr. Co.
June 10, 1982
M 92 - 44

251

Center 1/4 Corner of Sec. 4.
Set - 5/8" x 36" I.R., and alum. cap mkd. LS 498.
New BTs- 5" fir bears N.67°W.,30.6-ft.
4" fir bears S.2°E.,6.8-ft.
Note - Looked for and not found I.R. set by Markham (C.S.42/392). Ren. #99
6/10/82

252

Howard Johnstone
For: Roseburg Lbr. Co.
November 17, 1982
C.S. 58/188

1/4 Corner for Sections 15 and 22.
Found - 1966 County brass cap and iron pipe. Ren. #148
A 1" iron pipe. Ren. #34
30" cedar, S.7°W., 15.8 ft. Orig. bearing tree. (rescribed Ren.148
13" laurel, N.46°E., 23.0 ft. down. Ren. #148
New BT - 5" fir, N.24°W., 14.4 ft.

RE-RENEWED: SEE CORNER NO. #261

11/17/82

253

South 1/4 corner for Section 35 only of T.30-3
Found - Original hemlock corner tree is down and rotted. Remains of trunk show signs of a healed blaze (no scribing visible.) Also found a 1952 location poster on decayed trunk.
From the center of the decayed stump found a 1 1/2" diam. iron pipe, bears N.15°E., 1.0 ft. Ren. #60 of T.30-3
Found 1" iron pipe with brass cap set in Ren. #115 is along northerly side of iron pipe.
28" cedar now a decayed stump with scribing "S2 BTRE" visible bears S.29°E., 37.9 ft. from 1 1/2" I.P. (Rec. S.33°E., 37.2 ft. Ren. #60 and S.30°E., Ren. #115)
18" hemlock now 20" with healed blaze bears N.28°W., 40.0 ft. (Rec. N.30°W., 40.1 ft. Ren. #60 and N.33°W., Ren. #115) from the 1 1/2" iron pipe.
5" hemlock now 9" with well healed blaze bears N.58°E., 24.0 ft. (Rec. N.57°E., 24.2 ft.)from the 1 1/2" iron pipe. Ren. #115

Larry E. Monrean,
Deputy, Doug. Co.
Surveyors Office
Witness: J.M. Powell
July 11, 1983
C.S. 62/9

Set - As the iron pipe (1 1/2" diam.) from Ren. #60 of T30-3 is firmly set, I leave it in postion for the witness corner. I remove the found 1" diam. x 36" iron pipe with attached brass cap (Ren. #115). As this monument is in good condition I SET it in the true corner position and add the following "RESET 1983"
New BTs - 6" D. fir double blazed and scribed "S2 CS BT" bears S.37°E., 10.2 ft.
8" D. fir double blazed and scribed "S2 CSBT" bears S.23 1/2°W., 13.9 ft.
New bearings and distances to BTs from previous renewals:
20" hemlock bears N.26 1/2°W., 40.8 ft.
9" hemlock, bears N.56 1/2°E., 24.7 ft.
Note: Corner lies in E-W cutting line (timber to the north) approx 400 ft. west of road.

7/11/83

Howard W. Johnstone
Rsbg. Lumber Company
Ausust 23, 1985
M 99 - 36

Center 1/4 Section Corner for Sec. 20
Set - A 5/8" x 31" iron rod and aluminum cap, mkd. LS 498.
New BTs - 6" Fir, bears West 13.8 ft.
7" Cedar, bears N.30°E., 15.0 ft.
Both BTs properly scribed.

255

Section Corner for Secs. 13 and 24 only.
Found - 1966 County brass cap on 1" I.P. Ren. #170
60" Pine(dead) S.41½°W.,16.5' (Rec.S.44°W,15.7') Scar visible.(orig
8" Madrone N.66°W., 27.1' (rec.N.64°W,27.0') Scribe visible. (#170)
26" Fir N.71½°E., 16.5 ft. (Rec.N.70°06'E 15.9') Scar visible.
Hemlock (down) S.32°22'E., 34.7 ft. Ren. No. 170
9" Madrone S.29°E., 18.6' (Rec.S.28°23'E) Rotted Face.(Original)
New BT - 6" Fir which bears S.84°W., 12.2 ft. scribed T31S R3W S24 BT, with LS Washer No. 944 nailed to BT scribe.
Note: Record bearing/dists. given are from Survey M 79-43

Loyd R. Moffit
For: U.S.F.S.
Nov. 1986
C.S. 62/30

11/86