Douglas County Surveyor's Record of Government Corners Renewed

T 32 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

106

Corner #1 - Yellow King #2 Lode - Mineral Survey #792
Found - No trace of original Fir corner post.
An orig. 4" now 13" Madrone alive with faint scribe marks visible on previously opened rotten face, bears S. 76 1/4°E.. 17.7 ft. (Rec. S.83°48'E., 17.7 ft.)
An orig. 8" now 42" D. Fir alive with faint scar of well healed blaze visible bears N.1°W., 44.25 ft. (Rec. N.1°03'W 44.25 Ft.) We blaze and rescribe this tree "YK 2-1 MS 792 CS BT" on a double blaze along the westerly edge of the scar of the orig blaze.

Gary Langlitz
Frank C. Silagy
Doug. Co. Surveyors Office
April 26, 1978
C.S. 59/46

Set - At a point which agrees with the measurements to the above described orig. bearing tree, We SET a 1" x 30" I.P. 28" in the ground on a southwest slope, with brass cap attached marked: Douglas Co. Surveyor T 32 S / MS 792 / YK 2-1 / R 2 W / 1978

New BT - A 12" Madrone scribed "YK 2-1 MS 792 CS BT" on a double blaze bears S.57°E., 35.4 ft.

4/26/78

107

Corner #3, Mt. Top #2 and Corner #1, Mt Top #1, Mineral Survey #792
Found - No trace of original Alder corner post.
An orig. 14" D. Fir now a 20" stump with scribing "3 92" visible on previously opened blaze bears N.6°15'W., 20.80 ft.
An orig. 12" D. Fir now a 16" snag with well healed single blaze bears N.81°E., 15.60 ft. (Rec. N.74°11'E., 15.60 ft.)
Set - At a point which agrees with measurements listed for the found original corner accessories, WE SET a 1" x 30" I.P. 28" in the ground with brass cap attached marked: Douglas Co. Surveyor T 32 S / MT 1-1 / MT 2-3 / MS 792 / R 2 W / 1978

New BT's- An 8" D. Fir scribed "MT 1-1 MT 2-3 MS 792 CS BT" on a double blaze bears N.52 1/2°W., 14.9 ft.
A 20" P.Pine scribed "MT 1-1 MT2-3 MS 792 CS BT" on a double blaze bwars S.13°W., 60.3 ft.
Corner located about 20 ft. north of a dirt road.

Gary L. Langlitz, Doug. Co. Surveyors Office
Frank C. Silagy
May 2, 1978
C.S. 60/11

5/2/78

108

Corner #2, Mountain Top #2, Mineral Survey #792
Found - No trace of original cedar corner post.
An orig. 18" now 34" D. Fir alive with well healed single blaze bears S.56°W., 43.0 ft. (Rec. S.55°53'W., 43.0 ft.)
The original NE bearing tree, a 7" Laurel is gone.
Set - At a point which agrees with the record measurements to the only remaining orig. BT, previously described, WE SET: A 1" x 30" I.P. 27" in the ground with brass cap attached: Marked: Douglas Co. Surveyor T 32 S / 1978 / MT 2-2 / MS 792 / R 2 W

New BT's -An 18" D. Fir scribed "MT 2-2 MS 792 CS BT" on a double blaze bears S.25°E., 10.8 ft.
A 10" D. Fir scribed "MT 2-2 MS 792 CS BT" on a double blaze bears N.66 1/2°W., 21.5 ft.

1-79 5/2/78

PAGE NEXT