Douglas County Surveyor's Record of Government Corners Renewed

T 32 T.S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

173

1/4 Corner for Section 4 only, T.33-6 W.C.

Found - A 1" I.P. glush with ground, set by Wenderoth as South Wit. Cor. per Ren. #70. No other monuments found. The 1/4 Cor. and west wit. corners set by Wenderoth have been washed away by Cow Creek.

No original BTs or BTs per Ren. #6 (T33-6) found.

14" now 29" dia. Ash with double rotted out blaze facing 1/4 cor. position (Ren. #3, T33-6). BT is also SW BT to West wit. cor., wrongly identified as a maple, with a double partially healed blaze, scribing visible, facing position of Wenderoth West wit. cor. (Per Ren. #70)

NW BT per Ren. #3 (T33-6) is gone.

SE BT to West wit. cor. per Ren. #70 down and washed out of position.

Found BTs to South wit. cor. per Ren. #70:

36" now 43" dia. maple with a fully healed single blaze bears S.24°06'E., 78.0 ft. (REc. S.24°06'E., 76.5 ft. to face)

36" now 36" dia. I. Cedar with a fully healed single blaze bears S.58°05'W., 86.2 ft. (Rec. S.58°05'W., 84.4 ft. to face.)

Set - Computed N. 1/4 Cor. Sec. 4, T33-6W., as perpetuated by Eppstein and Wenderoth as evidenced by South Wit. Cor. (Ren. No. 70) and Ash (SW BT Ren. No. 3, T33-6) distance to Ash appears to be a face measurement. New West wit. cor. placed on a line between S. 1/4 S33 T.32-6 and computed position of N. 1/4 S4 T.33-6. A DCSO Brass cap protrudes 4" above ground. Cap stamped:

"Douglas County Surveyor" T33S
East
W.C. to Cor
1/4 S4 70.0 ft.
only
R6W
1986

The computed position for N. 1/4 S 4 bears East, 70.0 ft.

RE-RENEWED, SEE CORNER NO. #174

New Accessories:

29" Ash previously scribed by Eppstein and Wenderoth, bears S.21 3/4° E., 29.9 ft.

S. 1/4 Cor. S33, T32-6 (DCSO BC/I.P. bears West, 149.2 ft.

S. Wit. Cor. (1" I.P. Ren. No. 70) bears S.42½° E., 103.8 ft.

(Sketch of area on notes in file. See DCSO monument recovery quad books for coordiante information.)

Douglas County Surveyors Office
Randall Smith - Stephen J. Flause
May 23, 1986
C.S. 62/34

174

W.C. to 1/4 Corner for Sec. 4 only of T.33-6

Found - A 1" I.D. x 32" long iron pipe with a 1986 DCSO brass cap, bent and laying horizontal on top of ground, out of position, set as west witness corner per Ren. #173. BC/IP pulled out of ground by recent cat work.)

A 1" I.P. flush with ground set by Wenderoth as south witness corner per Ren. #70.

BTs and BOs to west witness corner:

14" now 29" dia. Ash with a doulbe rotted out blaze facing 1/4 position as per Ren. #3 (of T33-6), tree also is southwest BT to west witn. cor., wrongly identified as a maple, with a double partially healed blaze, scribing visible facing position of Wenderoth west wit. corner, per Ren. #70. Bearing tree bears S.21 3/4°E., 29.9 ft. from position of west wit. cor. as established in Ren. #173.

South 1/4 Cor. for S.33, T32-6 (DCSO BC/IP) bears West, 149.2 ft.

5/8" iron rod (east wit. cor. to S. 1/4 Cor. S33 T32-6) wrongly noted on sketch for Ren. #173 as a 1" I.P., bears West 109.2 ft.

South wit. cor., a 1" I.P. set flush with ground per Ren. #70 bears S.42½°E., 103.8 ft.

BTs to south witness corner per Ren. #70 are alive and in good shape. See Ren. #173.

Set - West wit. cor. established in Ren. #173 is reestablished from found accessories per Ren. #173. DCSO BC/IP per Ren. #173 is straightened and reset. DCSO BC/IP protrudes 6" above ground and is surrounded by a 18" dia. 6" high mound of stone. A white steel guard post is set 1 ft. east of west wit. corner. "RESET 1988 is added to brass cap.

New Accessory: 1" I.D. iron pipe (4" below ground with a 3/4" I.D. protrudin 14" and bent to ground, 3/4" I.P. along north edge of 1" I.P.) bears West 40.2 ft. (source unknown). 4/6/88

Douglas County
Surveyors Office
Randall W. Smith
Stephen J. Flause
Deputies
April 6, 1988
C. S. 62/52