Douglas County Surveyor's Record of Government Corners Renewed

33 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

5

C. Corner to Section 1 & 6.

Found - Rock as described, in mound of rocks.
Fir snag N. 46° E. 15.8 ft. Scribing visible "T 33 SR 4 & 5 W S 1 & 6 BT"
Fir snag S. 77° E. 10.6 ft. Part of face exposed, but no scribing visible.
Doug. Fir (now 15" diam.) S. 39° W. 26.4 ft. Scribing visible on previously opened face. "3S R 5 W S 1".-Tree in good condition. A vertical rock cliff approx. 10 ft high between this tree & corner.

Set - Brass Cap (on top of bedrock) Mkd: "County Surveyor's Office 1964 T 32 S R S 31 R 5 S1 | S6 4 W W T 33 S " Cap not oriented correctly thus - ⊣ Erect mound of rocks around pipe.

New BT: 9" Doug. Fir S. 65° E. 25.0 ft. Mkd: T 33 SR 4 W S 6 CS BT"
Corner lies on very steep, rocky NW slope.

Milo E. Godfrey, Dep. Surv.
Wm.Stoffel, Mike Darby, Mike Stone
June, 1964
C. S. File. No. 53/52

MICROFILM TO HERE 10/67

6

Closing Corner Sections 34 & 35, T32-4W.
The SE Sec. Cor. of Sec. 34, T32S, R4W was a stone which has been destroyed by a cat fire trail on a BLM timber sale. I replaced the corner as follows: Used compass and steel tape.
Set - 1" x 30" Iron Pipe, 10" above ground level
Two original bearing trees remain: 24" D.Fir bears 96 lks. dist.
30" D.Fir bears 50 lks. dist.

Lorne Swearingen
For. S.Ore.Ply
7/31/68
C. S. File
No. 55/85

7

Closing Corner to Section 4 & 5, T33-4W.
Found - 10", now 13" Cedar, N.27°E. (Rec.N22E) 5.3 ft., scribe visible.
18", now 22" Cedar, S.64°E. 5.3 ft., scribe visible.
6", now 9" D.Fir S.63°W. 24.4 ft., shows good scar.
24x12x8 Stone, mkd: "CC".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970 T32S T33S R4W CC S 33 / S 5 | S 4

New BT: 22" Laurel N.55°W. 14.5 ft. mkd: "T32S R4W S33 CS BT.
All other BT's O.K. and Tagged.
This corner lies about 70.0 ft. west of ravine.

6/17/70

8

Closing Corner to Sections 33 & 34, T32-4W.
Found - 30" Fir, now snag, N.37°W. 20.0 ft., scribe visible, burnt face.
No trace of other bearing trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970 T32S T33S R4W CC Douglas Co. S 33 | S 34 / S 4 Jack.Co.

New BT's: 4" D.Fir N.20°E. 9.7 ft., mkd: "S34 CC CS BT."
8" D.Fir S. 4°E. 14.5 ft. mkd: "T33S R4W S4 CS BT."
10" D.Fir N. 64°W. 42.5 ft. mkd: "T32S R4W S33 CC CS BT".
This corner lies on small spur, running south.

6/17/70

John M. Powell
W. Penley & J. Heritage
C.S. File No. 54/114

9

Standard Section Corner to Secs. 32 & 33 only, T32-4W.
Found - 40", now 40" Cedar, N.65°W. 17.2 ft., opened for scribe.
No trace of N. E. Bearing Tree
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970 T32S T33S R4W S SC / S 32 | S 33

Rblzd. & Rscbd: 40" Cedar N. 65° W. 17.2 ft mkd:"T32S R4W S SC S32 CS BT."
New BT: 24" Cedar N. 80°E. 69.8 ft. mkd: "T32S R4W S SC S33 CS BT".

6/17/70