T. 25S., R. 2W.

Renewal of ¼S 21 & 28

After logging in section 21 I found the original marked stone corner in place. The original bearing tree for section 21 is down & badly rotted. The original B. T. for section 28 is a rotten stub showing an old face but with scribing rotted away. The county surveyors B. T. for section 28 is living.

I drove a 1½" iron pipe 36" long 18" in the ground on the west edge of the corner stone, from which;

A maple 12" in diam. bears S. 13½°E. 34.3 ft.

(county surveyor's B. T. not re-marked)

A hemlock 10" in diam. bears N. 61°W. 21.0 ft.

marked ¼S 21 253 B. T.

Sept. 24, 1957

REGISTERED
OREGON
LAND SURVEYOR
V. W. Hosford
MAY 6, 1949
V. W. HOSFORD
253

FILED
RECEIVED
OCT 15 1957
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

340300

C. S. File No. 42/908-4