Dec 5, 1957

East 1/16 corner Sec. 11-14
T 28 S, R 5 W, W.M. as set
from G.L. File 49/21 : From
Hub 12-D I ran S 40°08½' W
116.63' to a ¾ x 24" I.P. which
I drove for 1/16 corner.
from which
15" W.O. bears N 3° W 64.0'
dist. mkd. 1/16 S 11 B.T.
12" B.O. bears N 50° E 48.0'
dist. mkd. 1/16 S 11 B.T.
A 4 way fence cor. bears N 5° E 7.0'
Road bears East 25.0'

REGISTERED PROFESSIONAL ENGINEER
2880
OREGON
NOV. 5, 1948
JOHN HOWARD MARKHAM, JR.

John H. Markham

See cor. 1-21-34 for note about FdIP

Work done for Stoman Lbr. Co.

42/321