Nov. 25, 1959

East 1/4 Corner Section 12
T31S R4W, W.M. as det. by O.B.T.
28" Fir N19E 40.3' O.B.T. — I
rescribed S7 T31S R3W B.T.
At corner point found 24"
Fir mkd. 1/4S on West face O.B.T.
set 1½"x48" I.P.
from which
6" Fir S84E 42.0' mkd. 1/4S7 R3W B.T.
7" Fir S75E 35.0' mkd. 1/4S7 R3W B.T.
12" Fir N29W 31.0' mkd. 1/4S12 B.T.
Road bears South 290.0' dist.
Witness: R.G. Boyd

REGISTERED PROFESSIONAL ENGINEER
2880
OREGON
NOV. 5, 1948
JOHN HOWARD MARKHAM, JR.

John H. Markham Jr.

Work done for Stoman Lbr. Co. ep

C. S. File No. 42/391