RENEW 1/6 — 28S
2N
SW R5W

FOUND ALL FOUR ORIG. BTS.
ORIG. 20" NOW 34" B. OAK
S 16° E 23.1' SHOWS GOOD SCARS
IT DO NOT OPEN. ORIG. 22" NOW
60" OAK, ROTTED, STUMP
N 20° E 115.5' WE OPEN & FIND
GOOD REVERSE SCRIBING "BT"
WE ALS FIND AXE WORK (OLD)
ON ROTTED STUMPS OF SW & NW BTS.

SET BRASS CAP AT COR. NW
COUNTY SURVEYORS OFFICE
1961 5/15/56
5/12/57 T28S
R5W R5W

NEW BTS.
RESCRIBE NOW 34" B. OAK S 16° E 23.8'
S 27 T28S R5W CS BT.

6" LAUREL BEARS S 55° W 44.0
SCRIBED S 12 CS BT

6" LAUREL BEARS N 23° E 86.2
SCRIBED S 6 CS BT

26" B.O. BEARS N 62° W 83.8
SCRIBED S 1 T28S R6W CS BT

VAR 20 ± 1°

J.D.
D.M.
J.P.

DIETZGEN NO. 385-6

C. S. File No. 41/64