R4W
RENEW CC $\frac{24}{25}$ T30S
COR. #96 R3W

FOUND — IRON BAR AT COR.
& BOTH BTS AS RECORDED
RESCRIBE N W BT CC S24
T30S R3W CS BT.
FENCES THUS



FEB. 28-1963 J.B. M.D.B.S.
VAR. 20½°

RENEW ¼ COR $\frac{19}{30}$ T30S R3W
COR. #31

FOUND — ORIG. 30" NOW 40" FIR
STUMP S 80° E 25.7 SHOWS
SCAR. 14" NOW 20" FIR N 53° E
42.9' SHOWS SCRIBING.
I.P.P. [illegible] AT COR. NOT FOUND
SET BRASS CAP AT CORNER MKD.
COUNTY SURVEYORS OFFICE 1963
¼ $\frac{S19}{S30}$ T30S R3W.

NEW BT 12" R. FIR BEARS S 44 W 15.0
SCRIBED ¼ S30 CS BT.
NOTE — COR. IS ON STEEP WEST
SLOPE 100' WEST OF DRAW.

March 1965

CS2113 & 51