SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 26 S RANGE 2 W

SECTION 8 CORNER CE 1/16

COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: --------

CORNER --------

ACCESSORIES:

	BEARING-	LINKS-	FEET-

M. C. Ramsey
R.S. No. 404

SURVEY RECORD

DATE: 1960

I. pipe 1" x 3' at corner from which

18" D. fir	N 46° E	19 links	(12.5)
28" D. fir	N 26° W	60 links	(39.6)

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION:

Corner pipe in good condition, but in cleared roadway and may be subject to damage or accidental loss.

Both BT's good condition, plainly scribed

From above identified CORNER ~~BKX~~: I find as follows: MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 46° E	11.6	1960	M.C. Ramsey B.T.; measured to face 16" D. fir
N 26° W	38.2	1960	" " " ; " " " 30" D. fir

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	~~BRG.~~ B.T.	"W" NAIL	PLATE	BRASS DISC
16" D. fir	N 46° E	11.6	Ramsey 1960	X	X	--
30" D. fir	N 26° W	38.2	"	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal and partly cleared in road construction

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) South ON MINUS (-) 2 %

FROM CORNER I

NORTH: + 30%; along top of ridge; uncut 40-50 year old D. fir 2nd growth

SOUTH: - 2%; 40' to forks of center line of logging road; 109° South and 25' West to old 1/16 Cor. stake; partially logged 2nd Gr fir to East; Uncut 2nd Gr. to West; good blazed line, Ramsey calls S 1° 28' W 21.28 ch to 1/16 Cor.

EAST: 0%; 30' to center line logging road bearing N 30° E; 2nd Gr fir and no cutting to North; partly cut 2nd Gr. fir to South; good blazed line, Ramsey calls N 85° 21' E 19.98 Ch. to East 1/4 Cor. of Sec. 8

WEST: - 11% for 70' thence breaks to steeper descent; 20' to centerline logging road bearing N 35° W.

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: [redacted] DATE: 6/22/61
ENGINEER - SURVEYOR
Land Agent

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS53/114-5