Renew 1/4 S27/S26 T25S R7W

Fd. 3/4 X 40" IRON Bolt see Ren. #29 for COR. & BTs as follows-
14" NOW 15" W. oak S. 89° W. $683^{\underline{0}}$ ft.
alive - shows good scars - This is
Frear's 1921 B.T. (see Ren. #4)
10" Now 14" apple S. 11° W. $395^{\underline{5}}$ ft. (slope)
alive - shows "1/4 S B" scribe on
unhealed Blaze - This Tree mkd by
Boyer in 1944 see CS 32/35. We
do not find any other Iron Bars or
Orig. B.T.s - Set in place of Iron Bolt.
1" I.P. & Brass cap mkd. "COUNTY
SURVEYOR'S OFFICE 1968 T25S
1/4 S27/S26 R7W" & Reset Bolt alongside
Brass cap. Mk. New B.T.'s -
4" Apple S. 66 [illegible] E. $85^{\underline{3}}$ ft.
Mkd. "1/4 S26 CS BT"
9" Ash N. 74° W. $111^{\underline{5}}$ ft.
Mkd. "1/4 S27 CS BT" (most southerly in clump of 5)
This cor. lies on old fence
line course E. & W. along old
unused Road.

Jan 31, 1968

V.R.T.
J.H.
V.P.
Chet Sorenson
of B.L.M.

#86 ○ V. R. Tracy

C. S. File No. 154/10283