Renew 1/4 520/521 T20S R7W
Fd. C.S. BRASS cap in place & ORig.
B.T. as Recorded in Rec # 63
in 1966 - Renewal B.T.s Both gone
at this Time due to Logging. Steel
fence post has been set by BRASS
cap. Since there are No Trees
for Several hundred ft we MK.
Stumps as follows -
30" D.FIR Stump N. 76 °E. 25 ½ ft,
MKd. "1/4 521 CS BT" also set 5/8" X 30" I.R.
20" deep in center of Stump.
30" FIR STUMP N 76 °W. 54 ½ ft,
MKd. "1/4 520 CS BT" & set 5/8" X 30" I.R.
20" deep in center of Stump. This
COR. lies Approx 80 ft N. of
CREEK course S. 60 °W. & 150 ft.
N. of Log access Road parallel To
CREEK.

May 6, 1968

V.R.T.
J.H.
V.P.

R T Bracy

O.K. J. C. S.

C. S. File No. 54/22-14