Renewal S30 | S29 T31S R5W
S31 | S32

Found:

26" Fir New stump S13W $59^{\underline{6}}$
Ripped over Face

22" Fir New blow Down S74E $180^{\underline{2}}$
Scribe visible "T31S R5W S32 BT".

26" Fir Stump, N12E $12^{\underline{0}}$
Scribe visible T31S R5W S29 BT

State Board of Forestry Brass cap

at Sec cor.

New Bearing Trees:

4" chinquapin N09E $23^{\underline{7}}$

scribed S29 CS BT

5" Fir S80W $70^{\underline{2}}$
Scribed T31S R5W S31 CS BT

5" Fir S8E $82^{\underline{1}}$
scribed S32 CS BT

Logging Rd Bears South 30°

Renewal #46

5-5-66

#73

*✓

C. S. File No. 54/25-2