Renew 1/4 532/533 T28S R2W

Fd. BT's as follows -

Orig. 9" Now 10" F.R S.72°W. 13½ ft.
Now Badly Rotted Stump - shows "BT" scribe on unhealed Blaze.

Orig. 10" Now 11" FiR N.32°E. 2.6 ft
Now Down - shows "B" fragmentary scribe on unhealed face. Set 1" IP & BRass Cap Mkd. "COUNTY SURVEYOR'S OFFICE 1966 T28S 1/4 532/533 R2W". Brass Cap is set in ground in axe notche on North side of 30" Log, Laying on COR. Location.

MARK New BTs as follows -
17" W. FiR N 31°E. 25¼ ft.
Mkd. "1/4 533 CS BT"
9" W. FiR S. 44°W. 31½ ft.
Mkd. "1/4 532 CS BT"

May 18, 1966

FILED
RECEIVED
MAY 18 1966
COUNTY SURVEYOR
DOUGLAS COUNTY, OREG.

U.R.T.
J.H.
F.J.

O #31

* O.K. J.W.B

C.S. File No. 54/26-6