Renewal

30|29
31|32

T31S R6W

Found:
3/4" I.P.P.
& BT's

15" D.Fir Now 34" N66E $8^{\underline{6}}$
Bark Scribed "T31S R6W" "S2" "T" "BT"

22" D.Fir Now Snag S6W $10^{\underline{6}}$
Bark Scribed "S0" "BT"

30" D.Fir Down Rotten N53W $76^{\underline{6}}$

14" D.Fir Stump Hole S70E $16^{\underline{5}}$

Renewed Along side I.P.P.
Set Brass cap at sec cor MKD.

County Surveyor's office

T31S R6W

S30|S29
S31|S32

New Bearing Trees

14" D Fir S27E $42^{\underline{5}}$
Scribed T31S R6W S32 CS BT

12" D Fir S60W $23^{\underline{9}}$
Scribed T31S R6W S31 CS BT

30" D Fir North $15^{\underline{0}}$
Scribed T31S R6W S30 CS BT

10-13-66

Renewal #27

DIETZGEN NO. 385-6

*②90

C. S. File No. 54/31-27