Renewal   S33 | S34 / S4 | S3   T21S / T22S R12W

Found:

24" Spruce now 36" stump (ROTTED) S85W 11^{9}
Scribe visible "S4" "T22" R12W

20" Spruce now 25" stump (ROTTED) N29W 34^{2}
Scribing Found R12W T22

No Trace of NE or SE BTs Also
No Trace of Iron Pipe at SW cor

Distances from orig BTs Taken From Faces

Renewal

Set Brass cap in 12" x 24" Tile at
Sec cor MKD

County Surveyors office

T21S R12W   AUG. 24-67

NOTE - TILE FILLED WITH CONCRETE.

S33 | S34 / S4 | S3   J. P. / J. B. / J. BYRON

T22S
1967

New Bearing Trees

38" Spruce   N 40 W 83^{1}
Scribed T21S R12W S33 CS BT

38" Hemlock   N 73 E 90^{2}
Scribed T21S R12W S34 CS BT

Also Power Pole for Bearing object

Power Pole   S 50 W 110^{2}
PP # R604A - 34

Note:
This cor lies in Middle of Draw running E&W. Also North of Forest Hills Rd Approx 125 ± (cor 22 3[illegible])

O#ID-T21-12
O 34

DIETZGEN NO. 355-6

C. S. File No. 34/47-5