Renewal #118 $\frac{21}{28}$ T223 R8W

Found:

30" W. Oak S57W 126 E

shows good scar

23" W. Oak S16E 123 E

shows good scar

Brass cap Bent by cat at

1/4 cor. Cap stamped wrong (Had

Sec 21 to the south + 28 to the

North.

Renewal

Reset Brass cap and Remark

same properly.

9-14-23

JMC

G. E.

J. G.

K. L.

O.K.

#128i

COUNTED

C. S. File No. 56/38-2

DIETZGEN NO. 385-B