Section 1/4 9 & 16 Twp. 29S Rge. 1E W

Date: 6-18-59

How was corner identified? BRASS CAP

Condition of corner: Yes this should have been 1E NOT 2E

Best route to reach corner: ROAD # 284 or 2826 or 272 W

C.S. File No. 5646-77

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

NO INFO ON BT'S

Signed #6 [redacted]