T 22S R 6W

1/4 S 33 | S 34

DATE: 4-21-77

____Condition Report Only
____Not Found
__X__Renewed
____Unrecorded
____Surveyed In
____Referenced Out

Previous Renewal #'s 82

Monument(s) Found: (Condition and Source) ORIGINAL STONE 3 INCHES ABOVE GROUND "1/4" MARKED ON WEST FACE. BRASS CAP ALONG S.E. EDGE OF STONE IS MARKED "COUNTY SURVEYOR'S OFFICE"

T 22S R 6W

1/4 S 33 | S 34

1961

Accessories Found: (Condition and Source)

ORIGINAL 20 NOW A 36 INCH DIAMETER CEDAR STUMP BEARS N 31° W 7.3 FEET (ORIGINAL S 31° W). STUMP IS BROKEN OFF, NO SCRIBING VISIBLE

NO OTHER B.T.'s FOUND AS AREA HAS BEEN LOGGED

#133 ✓



C. S. File No. 59/31-29 C

## RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

1. SET BRIDGE SPIKE IN A 42 INCH DIAM. R CEDAR STUMP. SPIKE BEARS N 71° W 41 5/10 FEET.

2. A D. FIR 10 INCH DIAMETER BEARS S 74 1/2° E 35 3/10 FEET. TREE DOUBLE BLAZED AND SCRIBED "1/4 S 34 C3 BT".

Location and Comments:
THIS CORNER LIES NEAR A N S CUTTING LINE. CORNER IS IN CLEAR CUT TO THE WEST OF LINE APPROX. 30 FEET.

20°E — Compass Declination
DCSO — Agency
LARRY E MONREAL — Party Chief
Larry L. Monreal — Notekeeper
P. L. EARLE — Witnesses

OK