CORNER RENEWAL

INTERNATIONAL PAPER COMPANY ENGINEER CREW

CORNER ¼ SEC. 28/33, T20 S, R 10 W, Will. Mer.

MONUMENT	RECORD	FOUND	SET
	2½" B.C on 36" X 1¼" I.P. PLS 497, 1982	Record B.C./I.P. in good condition	Nothing
ACCESSORIES	68" Fir brs. S02W, 19.5 Ft. to face	68" D-Fir stump, scribing visible, S02W 19.5 Ft.	Nothing
	24" Fir brs. N17 3/4 W, 5.6 ft. to face	24" D-Fir BT of record uprooted and slid down slope	—
			18" D-Fir stump with IPCO tag & nail bears N33E, 17.4 ft.

Date: 6/5/86

INTERNATIONAL PAPER CO.
P. O. Box 43
Gardiner, Or 97441
Phone: 503-271-3688

REGISTERED PROFESSIONAL LAND SURVEYOR

W. Carey Weatherly

OREGON
July 14, 1978
W. CAREY WEATHERLY
1667

C.S. File No. 63/37-5 C

#106 X