CORNER RENEWAL

INTERNATIONAL PAPER COMPANY ENGINEER CREW

CORNER 1/4 SEC. 3/2, T 23 S, R 9 W, Will. Mer.

RECORD	FOUND	SET
1980 2½" B.C. on 1¼"	Record B.C/I.P. in good	Nothing
I.P., PLS 1342	condition	
36" D.F., N 27 E, 19.8 ft.	40" D-Fir stump, partially	IPCO tag reads " S 27 W,
	healed over scribing visible	19.8 ft."
	N 27 E, 19.8 ft.	
42" D.F., S 66 E, 25.7 ft.	48" D-Fir stump, partially	IPCO tag reads "N 66 W,
	healed over scribing visible,	25.7 ft."
	S 66 E, 25.7 ft.	
30" D.F., N 62 W, 44.9 ft.	24" D-Fir stump, partially	IPCO tag reads "S 62 E,
	healed over scribing	44.9 ft."
	visible, N 62 W, 44.9 ft.	

MONUMENT

ACCESSORIES

Date: 5/6/86

INTERNATIONAL PAPER CO.
P.O. Box 43
Gardiner, Or 97441
Phone: 503-271-3688

REGISTERED PROFESSIONAL LAND SURVEYOR

W. Carey Weatherly

OREGON
July 14, 1978
W. CAREY WEATHERLY
1867

C.S. File No. 63/37-7