FILED

Date: 10/23/96 By: JP
This survey consists of:
Map: M 124-28
Narrative:
Corner Rpt: C.S. 65/8-9

DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 32 Township 32S Range 6W

County Douglas Date Oct. 11, 1996

Corner Designation

1/4 S

S32 & S33

___ Condition Report Only
___ Not Found
X Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals/Surveys, etc.

Douglas County Surveyor, George Wenderoth, 1955, (CS 47/24)
" " " , 1978

Monument(s) & Accessories Found: (Condition and Source)

Found 2½" Brass Cap on a 1" Iron Pipe, from which a:

12" O. Fir BT, new down & dead, bears N17°W, 33± feet.

Monument Detail

COUNTY SURVEYORS OFFICE
1/4 C
32 & 33
DEP L.S.S

Sketch

Monument Set (Procedures and Description)

None.

New Accessories

12" Madrona BT, I scribed "1/4 S33 BT" bears S18°E, 5± feet.
10" Oak BT, I scribed "1/4 S32 BT" bears N40°W, 10± feet.
6 Ft. Steel Fence Post, I set, bears North, 1± feet.
" " " " " " " bears South, 1± feet.

Location & Comments

Corner lies North, 150 feet from Old Robert Dollar Timber Access Road.

Compass Declination 20°E
Firm/Agency Shaner Engineering, Inc.
Address P.O. Box 1430 Roseburg, Oregon 97470
Party Chief B. Shaner
Notes B. Shaner
Witness David Snyder

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Bruce A Shaner

OREGON OCT. 4, 1957 BRUCE A. SHANER 430

Renews June 30, 1998

C.S. File No. 65/8-9