OREGON CORNER RESTORATION FORM

Corner No. 5

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation

S 1/16

S28 ● S27

X Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals/Surveys, etc. Corner Was set by RLS Price, Map No. CS 42/142, in 1956 & accepted by RLS Smalley, Map No. 117-48, in 1994.

Monument(s) & Accessories Found: (Condition and Source)

Found 1¼" Iron Pipe, from which a:
9" a. Fir BT, scribes visible, bears N33°W, 13.7 feet.
8" D. Fir BT, " " , bears S21°E, 36.1 feet.

Monument Detail

Sketch

FILED
Date: 3/27/2002 By: JC
This survey consists of:
Map: H 137-35
Narrative:
Corner Rpt: 65/42-11 thru 39

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

Set 6 foot steel fence post, South, 1.0 feet.
" " " " " " , North, 1.0 foot.

Location & Comments

Corner sets just above old mining access road.

Compass Declination 20°E
Firm/Agency Shaner Engineering
Address P.O. Box 1430
Roseburg, OR 97470
Party Chief B. Shaner
Notes " "
Witness Ben Schneider

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Bruce A Shaner
OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Renews June 30, 2002

C.S. File No 65/42-5