OREGON CORNER RESTORATION FORM

Corner No. 6

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation

1/4 S

528 ∅ 527

X Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals/Surveys, etc.

Corner was renewed by RLS Price, Map CS 42/142 in 1954 and " " by RLS Smalley, Map M117-48 in 1994.

Monument(s) & Accessories Found: (Condition and Source)

Found 1½" Iron Pipe, from which a:
30" Madrone BT, face overgrown, bears N15°W, 13± feet,
10" Chinquapin BT, " " , bears N60°E, 19± feet,
10" D. Fir BT, scribes visible, bears S13°E, 10± feet.
6" D. Fir BT, " " , bears S42°W, 13± feet.

Monument Detail

Sketch

FILED
Date: 3/27/2002 By: JC
This survey consists of:
Map: M137-35
Narrative:
Corner Rpt: 65/42-11 thru 39
DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

Set 6 foot steel post, West, 1± feet.

Location & Comments

Surveyor's Seal

Compass Declination 20°E
Firm/Agency Shaner Engineering
Address P.O. Box 1430
Roseburg, OR 97470
Party Chief B. Shaner
Notes " "
Witness Ron Schneider

REGISTERED PROFESSIONAL LAND SURVEYOR
Bruce A Shaner
OREGON OCT. 4, 1957 BRUCE A. SHANER 430

C.S. File No 65/42-16 Renews June 30, 2002