CORNER REPORT FORM

Section 2 Township 26S Range 2 W.W.M.

Douglas County Date April 26, 2004

CORNER DESIGNATION

N 1/16 S2|S1

✘ Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

Monument(s) & Accessories Found: (Condition and Source)

1/2" iron rod in mound of stone approximately 0.8 feet above grade.

12" (8") fir with double healed faces and tag, bears N30E, 13.3 feet.
24" (26") fir single healed face and tag, bears N62W, 16.8 feet.

Distances to found bearing trees were measured with tape at approximate side center of root crown. Trees were red band and face painted.

Monument Detail

1/2" iron rod

Sketch

Monument Set (Procedures and Description)

New Accessories

FILED
Date: 5/25/2004 By: JC
This survey consists of:
Map:
Narrative:
Corner Rpt: 65/49-37
DOUGLAS COUNTY SURVEYOR

Location & Comments

Corner falls on 90-100% east facing slope between two creeks. The main 4-6 foot wide fast flowing creek is approximately 30 feet north and flows S40E +/-. The secondary 3 foot +/- wide creek (not really visible until you are close) is approximately 15 east and flows N40E +/-. There is a small 10-15 foot wide pool where these two creeks intersect.

Compass Declination 19 East

Firm/Agency: i.e. Engineering, Inc.

Address: 741 SE Jackson
Roseburg, OR 97470

Party Chief: Bruce Webster

Notes:

Witness:

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
LARRY E. MONREAN
#1830

CERT. EXP. 12-31-04

C.S. File No 65/49-37