OREGON CORNER RESTORATION FORM

FILED
DATE: 7/15/2010 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS65/69-42

Section 36 Township 23 ~~24~~ South, Range 7 West
County Douglas Date 8 July 2010

Corner Description
North 1/4 Corner
Section 36

___ Condition Report Only
___ Not Found
X Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

DOUGLAS COUNTY SURVEYOR

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)
Found 3" IP Timberlands Aluminum cap dated 1994 with the following accessories:
31" D. Fir bears South 5.9' – bark scribing visible
16" D. Fir bears N49°E 15.4' – healed face

Monument Detail

Sketch
T23S R7W
¼ S25
S36
LS 2006
1994

Monument Set (Procedures and Description)
None

New Accessories
15" D. Fir bears N26°E 17.7' – blazed, scribed "X BT"
8" D. Fir bears S49°E 7.5' – blazed, scribed "1/4 S36 BT"

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 17° East
Firm/Agency Ward NorthWest Inc.
Address P.O. Box 105
Florence, OR 97439
Party Chief Ron Rice
Notes _____
Witness Josh Reed

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS. 12-31-2010

C.S. File No 65/69-42