FILED

Date: 6-11-2012 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/77-1

DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 5 Township 31 South, Range 9 West

County Douglas Date 8 June 2012

Corner Description

E 1/16

Section 5 & 32

___ Condition Report Only

___ Not Found

_X_ Renewed

___ Unrecorded

___ Surveyed In

___ Referenced Out

Previous Renewals / Surveys, etc.

C.S. 55 / 23

Monument (s) & Accessories Found: (Condition and Source)

No monument found

50" I. Cedar split snag S 41° W (record S 32 ½° W) 26.5' – no marks

24" D. Fir stump N 38° W (record N 31 ½° W) 17.4' - scribing visible

Monument Detail

Sketch

S32

E 1/16 •——

S5

2012

54633 LS

Monument Set (Procedures and Description)

Set 5/8" X 30" rebar with 2 ½" aluminum cap – marked as shown

Set by distance – distance intersection per record data C.S. 55 / 23

New Accessories

20" D. Fir bears S 61° W 8.8' – blazed, scribed E 1/16 S5 BT

16" D. Fir bears N 32° W 12.1' – blazed, scribed E 1/16 S32 BT

Location & Comments

Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East

Firm/Agency Northwest Land Surveying Inc.

Address P.O. Box 2827 Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness Jason Collver

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald L. Rice

OREGON JULY 9, 2002 RONALD L. RICE 54633LS

RENEWS: 12-31-2012

C.S. FILE 65/77-1