FILED
Date: 11/6/2012 By: JC
This survey consists of:
Map:
Narrative:
Corner Rpt: CS 65/77-49
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 33 Township 20 South, Range 9 West
County Douglas Date 30 October 2012

Corner Description
SE1/16
Section 33

___ Condition Report Only
___ Not Found
_X_ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap on iron pipe, dated 1984

67" D. Fir bears N 45-1/2° E 84.5' – healed face

(Record 9" Cherry missing)

Monument Detail

Sketch

Monument Set (Procedures and Description)
None

New Accessories
21" Alder bears N 55° W 16.4 ft. bark scribed, SE 1/16 S33 BT

Location & Comments

Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827
Florence, OR 97439
Party Chief Ron Rice
Notes
Witness Jason Collver

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/77-49