CORNER REPORT FORM

Section 14 Township 30S Range 3W

Douglas County Date 6-11-13

CORNER DESIGNATION

600500

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

DCSO 1963 & 1975

Monument(s) & Accessories Found: (Condition and Source)

FD DCSO 1963 BRASS CAP GOOD CONDITION

A 52" D. FIR S66 3/4 W 17.2 FT GOOD BLAZE

A 12" R. CEDAR N13 1/2 E 79.6 FT with DOUBLE BLAZE

A 26" HEMLOCK S7 1/2 E 21.9 FT with DOUBLE BLAZE

Monument Detail Sketch

FILED
Date: 6/12/2013 By: JC
This survey consists of:
Map:
Narrative:
Corner Rpt: CS 65/78-46

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

NONE

New Accessories

A 5" D. FIR N35°E 30.1 FT scribed

T30S R3W S12 BT

Location & Comments

Surveyor's Seal

Compass Declination 15°

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. FROMDAHL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-14

C.S. File No 65/78-46