FILED
Date: 6/15/2016 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/93-8

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 24 Township 20 South, Range 9 West
County Douglas Date 12 May 2016

Corner Description

E1/4
Section 24

_X_ Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found –2½" GLO brass cap on iron pipe, dated 1954

Record 14" decayed cedar snag bearing N 40-1/4° W 33.0' – down, burned
Record burned decayed hemlock stump bearing S 10-1/2° W 34.3' – no marks
13" X 6' D. Fir stump bears S 18-1/4° W 20.7' – scribe visible
13" X 6' D. Fir stump bears N 70-1/2° W 5.3' – scribe visible

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

Corner falls in recent logged and burned unit.

Placed steel posts adjacent to corner north and south.

High stump bearing trees have red painted band and face, plus bearing tree tag.

Location & Comments

Compass Declination 16° East
Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827
Florence, OR 97439
Party Chief Ron Rice
Notes _____
Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2016

C.S. File No 65/93-8