FILED
Date: 5-5-2020 By: JC
This survey consists of:
Map:
Narrative:
Corner Rpt: CS 65/106-3

DOUGLAS COUNTY SURVEYOR

CORNER REPORT FORM

Section 33 Township 31S Range 5W
Douglas County Date 3-2020
PLSS Number
400140

CORNER DESIGNATION

1/4 COR 33/34

- ☐ Condition Report only
- ☐ Not Found
- ☒ Renewed
- ☐ Unrecorded
- ☐ Surveyed In
- ☐ Referenced out

Previous Renewals/Surveys, etc:
DCSO 1966 CS 54#25-11 A. DeGroot 12/2019 M 171-74
Edwards 12/2018 M 175-11

Monument(s) & Accessories Found: (Condition and Source)
DCSO BRASS CAP
12" LIVE OAK N48°E 39.3 FT Nicked blaze
40" Fir S52°E 31.2 FT Visible bark scribe
12" Maple S44W 22.1 FT No marks

Monument Detail

Sketch

County Surveyors Office
T31S R5W
1/4 S33/S34
1966

Monument Set (Procedures and Description)

New Accessories
8" Madrone N25°W 24.8 FT scribed 1/4 S33 BT

Surveyor's Seal

Location & Comments
AREA Badly Burnt 2019

Compass Declination 15½°E
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470
Party Chief: N. Fromdahl
Notes:
Witness: L. Heddens

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1693
EXP 12-31-20

C.S. File 65/106-3