GOVERNMENT CORNER RESTORATION FORM

FILED
Date: 3/25/24 By: [illegible]
This survey consists of:
Map:
Narrative:
Corner Rpt: CS 67/62-29

DOUGLAS COUNTY SURVEYOR

TOWNSHIP 24S RANGE 8W SEC. 32 PLSS WM

DOUGLAS COUNTY OREGON DATE 3-23-26

Corner Designation
So 1/4 S32 only

Monument(s) Found: (Condition and Source)

2" pipe Cap on Iron pipe proj 6"

Previous Renewals

Chandler 1893 Vol 8 pg 3305
Wygant 1908 Vol 8 pg 3385
Reppeto 1975 CS 58/45
BLM Resurvey 1977-1979
Vol 42 pg 16433

__ Condition report
__ Not Found
✓ Renewed
__ Unrecorded
__ Surveyed In

MONUMENT DETAIL

S 1/4 S32

Accessories Found

11"x2FT Metal Capped Fir Stump N50 1/2 E 56.1FT Marks Rotted

Very Rotten 60"x5FT D. Fir Stump N30°W 73.9FT (BSD not checked)

21"x5FT Metal Capped Fir Stump N40°E 73.9FT partly Healed Single Blaze Scribes Visible

Steel Fence post 1FT East

pg 1/4

C.S. File CS 67/62-29

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

19" D. FIR S67°E 60.4FT Scribed
1/4 S32 on Double BLAZE

26" D. FIR S41°W 14.3FT Scribed
1/4 S32 on Double BLAZE

19" D FIR N87°W 34.8FT Scribed
1/4 S32 on Double BLAZE

3 1/2" MAG NAIL RIGHT Side Center
OF New Trees

Sketch of Monument, Accessories, and General Area

MON IS ON NEARLY FLAT
Ground in Very old Reprod.

Trimble GEO XT Location
43°.43266441 N
123°.67338432 W

Location & Comments

MON Approx
30 FT West of
Gravel Road

Comp. Decline. 14 1/4°E
Agency DCSO
Party Chief S. FLAUSE
Note keeper
Witnesses J Lorsung

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

CS 47/62-29 pg 2/4

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 8 Page(s) 3296)

Set Dogwood post 40" long, 5" dia., 18" in ground for the qr. sec. cor.on S. bdy. of sec. 32, from which
A Fir 40" dia., bears S.89°E., 81 lks. dist.
A Maple 10" dia., bears N.85°W., 17 lks. dist.

MINI GIS 43.43266°N 123.67337°W

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3305)

(29.42 chs.)
The old ¼ sec. cor. (found as described above)
(40.00 chs.) (West)
Set a post 3½ ft. long, 3" sq., 24" in the ground for ¼ sec. cor. on So. bdy. Sec. 32, mkd. ¼ S on N. face, from which
A Hemlock 6" dia.,bears N.27°E., 31 lks. dist. mkd. ¼ S BT
A Hemlock 8" dia., bears S.34°W., 42 lks. dist. mkd. ¼ S BT.

GLO survey by Morris Wygant, compassman for Zachariah M. Derrick, U.S. Deputy Surveyor, under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 8 Page(s) 3385)

(At 29.42 and 41.45 chains), "No trace of old ¼ sec. cor. can be found after diligent search".

Survey by Henry R. Reppeto - For: Weyerhaeuser Co. - March 6, 1975 - C.S. File 58/45

Set 2" x 3 ft. Iron pipe 2 ft. in the ground with brass cap stamped S¼ S32. Referenced by:
12" Fir N.50°30'E., 56.1 ft. "W" nail, W. Co. tag reads: Sec.32 T24S R8W 56.1 ft. S.50°30'W. to S ¼ Cor., scribed ¼ S32 BT.
72" Fir N.30°W., 70.3 ft. "W" nail, W. Co. tag reads: Sec. 32 T24S R8W 70.3 ft. S.30°E. to S ¼ Cor., scribed ¼ S32 BT.

BLM Resurvey by James E. Jelly; Harvey E. Wofford; Wayne L. Rogers, Cadastral Surveyors, under Group #'s 926 and 958 - Surveyed Aug. 1977/April 1979 - (DCSO records Vol. 42 Page(s) 16433)

(Cont. Next Page)

CS 67/62-29 pg 3/4

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description 43.43266441°N 3
DECLINATION 14'14°E 123.67338432°W 1/23/26

1977/1979 BLM RESURVEY

The ¼ sec. cor. of sec. 32 only, reestablished by proportionate measurement and recorded by Reppeto in 1975, and is accepted as the best available evidence of the position of the original corner, monumented with an iron post, 1½" dia., firmly set, projecting 8" above ground with brass cap mkd. "S 1/4 2" DIAM PROT. 6" S 32 PLUMBING CAP AT ROOT CROWN 56 10

from which the remains of bearing trees mkd. by Reppeto

METAL CAPPED 11" X 2 FT. BROKEN OFF

A Fir snag 10" dia., bears N.50½°E., 85 lks. dist. with scribe marks ¼ S32 BT visible on open blaze. MARKS ROTTED

VERY ROTTED 60" x 5 FT STUMP

A Fir ~~70" dia.~~, bears N.30°W., 112 lks. dist. with scribe marks ¼ S32 BT visible on bark 73 92 MARKS ROTTED AWAY TREES AND BRUSH ON LINE DO NOT CHKD

and a new bearing tree

21" x 5 FT. SAWN, METAL CAPPED STUMP

A Fir 20" dia., bears N.40°E., 112 lks. dist., mkd. ¼ S32 BT. PHSB ALL SCRBG. VISIBLE 73 92

A STEEL FNC. PST. BEARS EAST, 1 FT.

NEW REFERENCES:

A 19" DIAM. D. FIR SCRIBED "1/4 S32" ON A DBL. BLZ.; BEARS S67°E, 60 4 FT. DIST

A 26" DIAM. D. FIR " " " ; BEARS S41°W, 14 3 FT. DIST.

A 19" DIAM D. FIR " " " ; BEARS N87°W, 34 8 FT. DIST.

MONUMENT IS ON NEARLY FLAT GROUND IN VERY OLD REPROD. FOREST AND APPROX. 30 FT WEST OF GRAVEL ROAD.

CS 47/42-29 pg 4/4